

Project: DD2090 4CAM FFC Current Revision: ROMOEO Assembly variant: [No Variations] DD2090 4CAM FFC Revision History: Revision

Reason for Change

DM1099FFC R1M0E1-> DD2090 4CAM FFC R0M0E0

1) Changed SoM to BW2099
2) Added MIPI CAM D (4 lane)
3) Added uSD card
4) Added Software controll over FSIN signal between the 2 lane and 4 lane cameras (US)
5) Added ESD protection on USB signals **Changes Implemented Date** 10 June 2021

Title DD2090 4CAM FFC		Luxonis Holding 1925 Harmony Park Drive	
Size: Tabloid Number: D0000190	Revision:R0M0E0	Westminster, ČO 80234	
Date: 30/07/2021 Time: 13:09:37	Sheet 2 of 10	United States	_















