Project: BW10980BC Current Revision: R1M0E1 BW1098OBC Revision History: Date 10/21/2019 Revision Initial release **Reason for Change Changes Implemented** Decoupling capacitors too close to OV9282 camera module body
 Overlay on OV9282 camera module body too wide and should match outline
 of module body
 Left/Right camera convention doens't match verbiage in schematic 1) Moved C7, C8, C9 and C12 a bit farther from the J3 (Left) camera module. Moved C23 and C25 a bit farther away from J9 (Right) camera module.
2) Updated the overlay for right and left OV9282 camera modules so that it outlined the 3D Body layer. Thi should match the camera module body outline and make it easier to mount and aligne the modules. 11/27/2019 R0M0E0 -> R1M0E1 Title BW1098OBC Luxonis Holding 1925 Harmony Park Drive Westminster, CO 80234 Size: Tabloid Number:DXXXX RevisionR1M0E1 Date: 11/27/2019 Time: 11:17:11 AM Sheet1 of 8
Drawn by: Brian Weinstein













