

Industrial Safety and Lockout/Tagout Guide

Synthetic project reference document for Phase 5 RAG testing.

1. Safety Principle

Maintenance personnel must follow the site's approved safety procedures and applicable regulations. This project reference does not replace employer procedures, equipment manuals, or legal requirements.

2. Energy Isolation

Before maintenance, identify all hazardous energy sources. These may include electrical, mechanical, hydraulic, pneumatic, thermal, and stored energy. Apply the site's approved lockout/tagout process.

3. Verification

After isolation, verify that the machine cannot start or move unexpectedly using the approved verification method. Only authorized personnel should perform the procedure.

4. Sensor and AI Alerts

An AI anomaly alert is an indication for investigation, not permission to enter a hazardous area. A low-risk AI result does not prove that a machine is safe. Safety decisions require approved procedures and qualified human judgment.

5. Return to Service

Before restoring energy, confirm that guards and protective devices are installed, tools and personnel are clear, maintenance work is complete, and the approved return-to-service procedure has been followed.

Important: This is synthetic reference content created for software testing and demonstration. It is not a manufacturer manual or a substitute for approved maintenance procedures, qualified personnel, or applicable safety requirements.