

02.04.2021 AB4-LT



## Виброскорость: 12.14



Версия V0.0.9

Requesting bluetooth device...

"AB4-LT #F88A5EA2ABA5" bluetooth device selected

Connecting to GATT server...

Service found, getting characteristic...

 $0000aa81\text{-}0000\text{-}1000\text{-}8000\text{-}00805f9b34fb}\colon 0$ 

0000aa82-0000-1000-8000-00805f9b34fb: 0

0000aa84-0000-1000-8000-00805f9b34fb: 0

0000aa85-0000-1000-8000-00805f9b34fb: 0

Characteristic found

Starting notifications...

Notifications started

Readingcoefficient ...

coefficient 10300

rawdata start

однократно

HZ1600

9.26

fftsave to csv

rawdata start

02.04.2021 AB4-LT

однократно

HZ1600

15.4

fftsave to csv

fftstart

однократно

5.88

fftstart

однократно

5.19

fftsave to csv

fftstart

однократно

HZ1600

12.14

fftsave to csv

"AB4-LT #F88A5EA2ABA5" bluetooth device disconnected, trying to reconnect...

Connecting to GATT server...

Service found, getting characteristic...

TypeError: service.getCharacteristic is not a function