
uCommander: the UDS service tool

uCommander is a software tool aimed at providing secure and easy access for update of ECU firmware, certificates and other maintenance or configurations tasks while supporting multiple AEPL projects

Team

Eshwar eshwar.jorvekar@accoladeelectronics.com

Abdullah muhammed.shaikh@accoladeelectronics.com

Rohini rohini.jadhav@accoladeelectronics.com

Legend: Stable build QA build hotfix

Release Notes **v0.3.0:**

31 May 2024

Tested Against

- TCU (chetak) Bootloader version AE_BA001_PBL_A_0.0.5_B01.

Added

- Project configurations loaded automatically according to selected project from drop-down
- User can override CAN IDs for development purposes after selecting the project

Fixed

- Debug window can now be used and will not freeze the application.
- Reset ECU button will no longer make the application unresponsive.
- In case of "Project: Gradient Sensor" app used to reply with id 0x18DA33F irrespective of the provided can id.

Release Notes **v0.2.1:**

17 April 2024

Added

- Added support for custom fonts.

Fixed

- The UI flow allows consecutive flashing.
- Black window will not be launched while running the exe.

Open Issues

- Boot lock unresponsive sometimes. (Few buttons unresponsive for communication timeout duration)

Release Notes **v0.2:**

15 April 2024

Added:

- UI and UX improvements
- Generic support added for TCU (Sibros) and Gradient Sensor projects that can be done by setting correct ids

id	TCU (Sibros)	Gradient Sensor
Tester id	CDA33F1	18DA33F1
ECU id	CDAF133	18DAF133
Boot lock	required	not required
Min sw ver	Bootloader: PBL_0.0.4	Bootloader: GSB_3.1.1_TST01 App: GS_3.1.2_TST01

- Consecutive flashing supported
- Progress bar for current file percentage complete

Fixed

-
- The UI flow allows consecutive flashing

Release Notes v0.1.0:

29 March 2024 (TCU Sibros only)

- UDS flashing with 29-bit id. Currently only firmware upload is supported
- Bootloader locking from TesterPresentSvc supported
- File browse and transfer supported
- ECU reset supported
- Basic debug log window

Known limitations

- User will see a black window when launching the exe, to be addressed soon
- UI may become unresponsive when clicked Boot Lock or ECU Reset
- The UI flow does not allow consecutive flashing, to be addressed soon