

Legend:

Stable build

QA build

Patch or bugfix

Release Notes:

Stable build 12 Feb 2024 v1.4.0

- Added support for TCU ethernet serial firmware and certificate upgrade support

Project	Firmware series	Certificate support
TCU ethernet	6.2.x	Minimum 6.2.0

QA build 11 Jan 2024 v1.3.0

- Added support for Wifi Data Logger serial firmware upgrade
- Software checks will prevent cross flashing. QA to test with all possible scenarios
- TCU4G - Telematics Control Unit 4G
- PDL - Power Train Data Logger
- WDL - Wifi Data Logger

Project	Firmware series	Certificate support
TCU4G	5.x.x	Minimum 5.2.7 required
PDL	2.x.x	Minimum 2.0.14 required
WDL	1.x.x	Not required by product

Stable build 22 Nov 2023 v1.2.1

Build marked stable with no changes

QA build 07 Nov 2023 v1.2.1

- Fixed ATCU-2880, project version check bug fixed
- External battery checks updated at (minimum for flashing) IBAT 3.6V EBAT 8V

QA build 02 Nov 2023 v1.2.0

- Fixed ATCU-2862, shifted the firmware and version detection mechanism in comm thread
- Refer **service tool v1.2.0 testing.xlsx** for feature wise test guidelines and **test_files.zip**

QA build 18 Oct 2023 v1.1.0

- Added support for PDL firmware and certificate flashing
- User must ensure firmware support before flashing certificates
- Cross flashing not allowed from utility. TCU bin not allowed be flashed to PDL and vice versa. Software checks will prevent cross flashing. QA to test with all possible scenarios

Project	Firmware series	Certificate support
TCU4G	5.x.x	Minimum 5.2.7 required
PDL	2.x.x	Minimum 2.0.14 required

Stable build 18 Sept 2023 v1.0 (TCU4G only)

- Added project combobox for future projects. Currently only 'TCU4G' is supported
- User can now select .tar, .zip or .bin file for firmware upload during file browse
- Mains voltage above 10V required and internal battery must be present before firmware upload

QA build 12 Jul 2023 v0.2 (TCU4G only)

- Added firmware flashing support with backward compatibility
- Bin file renaming and FOTA.txt updating not required
- Added internal battery checks before FOTA
- Added checks for file names before flashing certificates and compatibility check
- Max cert len considered 6kb per certificate
- Protocol compatible with "v0.3 dfu and certificate upgrade protocol specifications.pdf"
- File names must be fixed for certificates due to lack of metadata (natural limitation) ca.pem cc.pem ck.pem
- Implemented CRC16, chunk retry and speed improvements

- Multiple sessions supported

QA build 10 May 2023 v0.1 (PDL only)

- Engineering version for serial certificate flashing
- PDL compatibility: Minimum AEPL firmware version 5.2.4.47 and above requiredProtocol reference "MQTT_fota_docs_revised1.1.pdf"
- Data integrity (CRC) not implemented during transfer
- Known issue: Need to restart service tool every time for new flashing
- Known issue: In case of GUI unresponsive, rewrite the certificates again

Team

UI and UX:

Eshwar eshwar.jorvekar@accoladeelectronics.com

AEPL firmware:

Aditya aditya.prajapati@accoladeelectronics.com Aarti aarti.bhelke@accoladeelectronics.com

New requirements:

Abdullah muhammed.shaikh@accoladeelectronics.com