

Pre Shipment Inspection Report

(Non-negotiable)

Inspector: Min Tang

Inspection location: Jiaxing City, Zhejiang Province

Date of inspection: Aug 21, 2023



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.





Non-negotiable



Contents


| 1. Background information | 3 |
|---|----|
| 2. Sample description | |
| | |
| 3. Instrument | |
| 4. Quantity check | 4 |
| 5. Technical document check : | 5 |
| 6. Visual inspection | 5 |
| 7. Maximum power determination | 8 |
| 8. Insulation test | 11 |
| 9. Continuity test of equipotential bonding | 12 |
| 10. Other items | 14 |
| 11. Product ID for this batch | 14 |
| 12 Photos | 46 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND







Page 3 of 50



1. Background information

| SGS order No.: | IN-QD-PV-23146-179 | | |
|----------------|--------------------|------------|-------------------|
| Coordinator: | Young Yang | Telephone: | +86 532 6899 9116 |
| | | | |

Description of commodity

Mono Solar Module -LR5-72HTH-575M

Buyer

GARIBSONS (PVT) LTD

C-69/71, 12TH COMMERCIAL STREET, PHASE II EXT, DHA, KARACHI 75500, PAKISTAN

Supplier

LONGI SOLAR TECHNOLOGY CO.,LTD

NO.8369, SHANGYUAN ROAD, CAOTAN ECOLOGICAL INDUSTRIAL PARK, ECONOMIC AND TECH NOLOGICAL DEVELOPMENT ZONE, XIAN, SHAANXI, CHINA.

| 308-1037-C012 |
|---------------|
| 068 |
| |

LC Issue Date N/A

| | Item | Satisfactory | Non conforming | Rejected | Subject to buyer's evaluation |
|-------------|--------------------------|--------------|----------------|----------|-------------------------------|
| | Quantity check | • | | | |
| | Technical document check | • | | | |
| Nature of | Visual inspection | • | | | |
| | Maximum power | | | | |
| inspection: | determination | • | | | |
| | Insulation test | • | | | |
| | Continuity test of | | | | |
| | equipotential bonding | • | | | |
| | Other items | • | | | |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Sample description

| General information | | | |
|--|---------------------------|--|--|
| Abbreviations | | | |
| STC-Standard test environment | FF- Fill factor | | |
| Pmax-Maximum power | Imp-Maximum power current | | |
| Voc-Open circuit voltage | Isc-Short circuit current | | |
| Vmp- Maximum power voltage | EffModule efficiency | | |
| EL-Electroluminescence | / | | |
| Determine | | | |
| The test condition is not suitable for this test product | N/A (Not applicable) | | |
| The test sample meets the requirements | P (Pass) | | |
| The test sample does not meet the requirements | F (Fail) | | |

Instrument

During the inspection, the following instrument calibration status has been checked for inspection:

| No | Name | ID No. | Measuring | Calibrated | Certificate NO. |
|----|---------------------------|-------------------|------------|-------------|-----------------|
| | Name | ID NO. | range | (Yes/No/NA) | (Optional) |
| 4 | Tono | LONGI-JXQ-L-2207 | 0~5M | Voc | LGiLE-Q-QED-0 |
| ' | Tape | LONGI-JXQ-L-2207 | U~5IVI | Yes | 55-F01 V03 |
| 2 | IV Instrument calibration | GS20A261622111000 | High LIGHT | Yes | GXgf2023-01433 |
| | report | G320A261622111000 | SMT | 165 | GAGI2023-01433 |
| 3 | Safety Instrument | 9980ALG2209218 | N/A | Yes | 1JA22005130-00 |
| | calibration report | 9900ALG2209216 | IN/A | 162 | 18 |

4. Quantity check

4.1.Reference documents:PO NO.: N/A

4.2. Method of quantity check: Total carton counting.

Order quantity:

| No. | Description | REQ. quantity | ACT. quantity | Remark |
|-----|-------------------|---------------|---------------|--------|
| 1 | Mono Solar Module | 2880Pcs | 2880Pcs | N/A |
| 1 | LR5-72HTH-575M | 2000FCS | 2000FGS | IN/A |

Note:



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND





The result of quantity check was satisfactory.

5. Technical document check:

Factory provided below technical document according to IEC61730-1/-2:2016&IEC61215-1/-2:2 016.SGS inspector checked and found acceptable .

| File name | Serial number | Date of issue | Validity date |
|--------------------------------------|------------------------|---------------|---------------|
| IEC_61215_61730_2016 report | 704061700516-21 | 2022-06-28 | N/A |
| IEC_61215_61730_2016 certificate | Z2 099333 0045 Rev, 23 | 2022-09-08 | 2027-09-07 |
| IV Instrument calibration report | GXgf2023-01433 | 2023-03-04 | 2024-03-03 |
| Safety Instrument calibration report | 1JA22005130-0018 | 2022-10-24 | 2023-10-23 |
| ВОМ | N/A | N/A | N/A |

6. Visual inspection

- 6.1. Reference documents: IEC61730-2:2016
- 6.2. Sample size: ISO 2859-1 at the sample plan of General inspection S-4, Sample size 32 pcs, AQL 0.According to the requirement, SGS inspector performed visual inspection for the randomly chosen
- 32 pcs of PV modules in a well illuminated area and 60-80cm distance.

Details as Follows:


| Items name | Visual inspection |
|-------------|--|
| | IEC61730-2:2016 Photovoltaic (PV) module safety qualification –Part 2: Requirements |
| | for testing |
| | MST 01Visual inspection: |
| | Carefully inspect each module under an illumination of not less than 1 000 lux for |
| | conditions and observations as defined in IEC 61215-1.: |
| | a) broken, cracked, or torn external surfaces; |
| | b) bent or misaligned external surfaces, including front sheet, back sheet, frames and |
| Technical | junction boxes to the extent that the safety of the PV module would be impaired; |
| requirement | c) in cemented joints bubbles or delamination with closest distances to each other \leqslant |
| | 2 times the minimum required distance through cemented joint (see Tables 3 and 4 of |
| | IEC 61730-1:2016) shall be evaluated as conductive and electrically connected. The |
| | shortest distance from and to such bubbles or delamination through insulation material |
| | shall in sum not be shorter than the required minimum distance through cemented joint. |
| | d) for adhesive bonds other than in c) bubbles or delamination with closest distances to |
| | each other $\leqslant2$ times the minimum required creepage distance (see Tables 3 and 4 of |
| | IEC 61730-1:2016) shall be evaluated as conductive and electrically connected. The |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 6 of 50

Non-negotiable



shortest distance from and to such bubbles or delamination through insulation material shall in sum not be shorter than the required minimum creepage distance.

- e) loss of mechanical integrity to the extent that the safety of the installation and safe operation of the PV module would be impaired;
- f) if the mechanical integrity depends on lamination or other means of adhesion, the sum of the area of all bubbles shall not exceed 1 % of the total PV module area;
- g) evidence of any molten or burned component;
- h) markings not complying with 5.2 of IEC 61730-1:2016 and the durability of markings test (MST 05) at final inspection;
- i) edges not complying with MST 06 sharp edge test at final inspection.

| | i) edges not complying with wor of sharp edge test at final hisp | ection. | |
|------------------|--|---------|--|
| Test time | Aug.21, 2023 | | |
| Sample No. | Visual description | Result | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 21417 | No major visual defects found | Pa55 | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 24475 | No major visual defects found | r ass | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 19343 | No major visual defects found | 1 400 | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 19361 | The major visual delecte realing | | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 19337 | The major visual delicate realing | | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 24472 | The major visual delecte realing | | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 19336 | | | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 19338 | , | | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 19364 | , | | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 19339 | , | | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 19342 | , | | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 24425 | , | | |
| LRP0041312307017 | No major visual defects found | Pass | |
| 19325 | , | | |




The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx, Attention is drawn to the limitation of ilability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 7 of 50

Non-negotiable

| 4 | 7 | 1 | M | |
|-----|----------|---------|------|---|
| - 1 | F- | 11 . | 9: | |
| | | W T | | 3 |
| - 4 | The same | Visited | 1 45 | |


| 19316 | LRP0041312307017 | No major visual defects found | Pass |
|---|------------------|--------------------------------|---------|
| 19327 | 19316 | | |
| LRP0041312307017 | | No major visual defects found | Pass |
| 24491 No major visual defects found Pass LRP0041312307017 24524 No major visual defects found Pass LRP0041312307017 19308 No major visual defects found Pass LRP0041312307017 24303 No major visual defects found Pass LRP0041312307017 24403 No major visual defects found Pass LRP0041312307017 24401 No major visual defects found Pass LRP0041312307017 24399 No major visual defects found Pass LRP0041312307017 24490 No major visual defects found Pass LRP0041312307017 24546 No major visual defects found Pass LRP0041312307017 19331 No major visual defects found Pass LRP0041312307017 19330 No major visual defects found Pass LRP0041312307017 19329 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass | | , | |
| LRP0041312307017 | | No major visual defects found | Pass |
| 24524 No major visual defects found Pass LRP0041312307017 19308 No major visual defects found Pass LRP0041312307017 19333 No major visual defects found Pass LRP0041312307017 24403 No major visual defects found Pass LRP0041312307017 24401 No major visual defects found Pass LRP0041312307017 24399 No major visual defects found Pass LRP0041312307017 24490 No major visual defects found Pass LRP0041312307017 24546 No major visual defects found Pass LRP0041312307017 19331 No major visual defects found Pass LRP0041312307017 19330 No major visual defects found Pass LRP0041312307017 19329 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass | | · | |
| LRP0041312307017 No major visual defects found Pass LRP0041312307017 No major visual defects found Pass | | No major visual defects found | Pass |
| 19308 | | , | |
| LRP0041312307017 No major visual defects found Pass | | No major visual defects found | Pass |
| 19333 | | , | |
| 19333 LRP0041312307017 No major visual defects found Pass | | No major visual defects found | Pass |
| 24403 No major visual defects found Pass LRP0041312307017 24401 No major visual defects found Pass LRP0041312307017 24399 No major visual defects found Pass LRP0041312307017 24490 No major visual defects found Pass LRP0041312307017 24546 No major visual defects found Pass LRP0041312307017 19331 No major visual defects found Pass LRP0041312307017 19330 No major visual defects found Pass LRP0041312307017 19329 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass | | , | |
| LRP0041312307017 No major visual defects found Pass | | No major visual defects found | Pass |
| 24401 No major visual defects found Pass LRP0041312307017 24399 No major visual defects found Pass LRP0041312307017 24490 No major visual defects found Pass LRP0041312307017 24546 No major visual defects found Pass LRP0041312307017 24395 No major visual defects found Pass LRP0041312307017 19331 No major visual defects found Pass LRP0041312307017 19329 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass LRP0041312307017 No major visual defects found Pass | | , | |
| 24401 LRP0041312307017 No major visual defects found Pass | | No maior visual defects found | Pass |
| 24399 No major visual defects found Pass LRP0041312307017 24490 No major visual defects found Pass LRP0041312307017 24546 No major visual defects found Pass LRP0041312307017 19331 No major visual defects found Pass LRP0041312307017 19330 No major visual defects found Pass LRP0041312307017 19329 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass | | | |
| 24399 LRP0041312307017 No major visual defects found Pass | LRP0041312307017 | No major visual defects found | Pass |
| 24490 No major visual defects found Pass LRP0041312307017 24546 No major visual defects found Pass LRP0041312307017 24395 No major visual defects found Pass LRP0041312307017 19331 No major visual defects found Pass LRP0041312307017 19329 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass | 24399 | | . 400 |
| 24490 LRP0041312307017 No major visual defects found Pass | LRP0041312307017 | No major visual defects found | Pass |
| 24546 No major visual defects found Pass LRP0041312307017 24395 No major visual defects found Pass LRP0041312307017 19330 No major visual defects found Pass LRP0041312307017 19329 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass | 24490 | No major visual deleste found | 1 455 |
| 24546 LRP0041312307017 No major visual defects found Pass | LRP0041312307017 | No major visual defects found | Pass |
| 24395 No major visual defects found Pass LRP0041312307017 19330 No major visual defects found Pass LRP0041312307017 19329 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass LRP0041312307017 19315 No major visual defects found Pass | 24546 | No major visual defects found | 1 833 |
| 24395 LRP0041312307017 No major visual defects found Pass | LRP0041312307017 | No major vicual defects found | Pacc |
| 19331 No major visual defects found Pass | 24395 | No major visual defects found | F d 5 5 |
| 19331 | LRP0041312307017 | No major vigual defects found | Door |
| No major visual defects found LRP0041312307017 | 19331 | No major visual defects found | Pass |
| 19330 LRP0041312307017 No major visual defects found Pass LRP0041312307017 No major visual defects found Pass LRP0041312307017 No major visual defects found Pass | LRP0041312307017 | No maior de la facta forma | Dana |
| No major visual defects found Pass LRP0041312307017 No major visual defects found Pass LRP0041312307017 No major visual defects found Pass | 19330 | No major visual defects found | Pass |
| 19329 LRP0041312307017 No major visual defects found Pass LRP0041312307017 No major visual defects found Pass | LRP0041312307017 | No maior viewal defeate formal | Dana |
| 19315 No major visual defects found Pass LRP0041312307017 No major visual defects found Pass | 19329 | No major visual defects found | Pass |
| LRP0041312307017 No major visual defects found Pass | LRP0041312307017 | No section to all the district | 5 |
| l No maior visual defects found I Pass | 19315 | No major visual defects found | Pass |
| No major visual detects found Pass 24492 | LRP0041312307017 | | |
| | 24492 | No major visual defects found | Pass |
| LRP0041312307017 | LRP0041312307017 | | _ |
| No major visual defects found Pass | 24466 | No major visual defects found | Pass |
| LRP0041312307017 | LRP0041312307017 | | _ |
| No major visual defects found Pass | | No major visual defects found | Pass |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 8 of 50

Non-negotiable



| Remarks | See annex for visual pictures. |
|---------|--------------------------------|
|---------|--------------------------------|

| Defect description | Major |
|--------------------|-------|
| | 0 |
| Total Found | 0 |
| Maximum allowed | 0 |

Note:

Following visual issues found during the inspection subject to client (user decision) due to no specified regulation in SRO604 program.

| Other visual found | Quantity |
|--------------------|----------|
| | 0 |
| | 0 |
| Total Found | 0 |

The result of visual quality check was satisfactory.

Maximum power determination

- 7.1 Reference documents:IEC61215-2:2016
- 7.2. Sample size: ISO 2859-1 at the sample plan of General inspection S-4, Sample size 32 pcs, AQL

According to the requirement, SGS inspector performedmaximum power determination for the randomly chosen 32 pcs of PV modules.

Details as Follows:

| Items name | Maximum power determination |
|-------------|---|
| | IEC61215-2:2016 Terrestrial photovoltaic (PV) modules - Design qualification and |
| | type approval –Part 2: Test procedures |
| | MQT02Maximum power determination: |
| Technical | a) A radiant source (natural sunlight or a solar simulator class BBA or better in |
| requirement | accordance |
| | with IEC 60904-9). |
| | b) A PV reference device in accordance with IEC 60904-2. If a class BBA simulator or |
| | betteris used, the reference device shall be a reference module of the same size with |




IND-F-OPS-05-21 [V:03, Jul 1st, 2017]

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

www.sgsgroup.com.cn



Page 9 of 50

Non-negotiable

the samecell technology to match spectral responsivity. If such a matched reference device is notavailable one of the following two options need to be followed:

- 1) a Class AAA simulator shall be utilized, or
- 2) the spectral responsivity of the module according to IEC 60904-8 and the spectraldistribution of the solar simulator need to be measured and the module data corrected according to IEC 60904-7.
- c) A suitable mount for supporting the test specimen and the reference device in a planenormal to the radiant beam.
- d) Apparatus for measuring an I-V curve in accordance with IEC 60904-1.


| Test time | Aug.21, 2023 | | | | | | | |
|---------------------------|--------------|------------|------------|------------|------------|------------|-----------|--|
| Sample No. | TEMP (°C) | Voc (V) | Isc (A) | Vmp (V) | Imp (A) | Pmp (W) | FF (%) | |
| LRP0041312307017 21417 | 25.44 | 52.200 | 14.261 | 43.349 | 13.338 | 578.206 | 77.67% | |
| LRP0041312307017 24475 | 25.9 | 52.208 | 14.332 | 43.392 | 13.338 | 578.784 | 77.35% | |
| LRP0041312307017 19343 | 25.8 | 52.128 | 14.368 | 43.306 | 13.338 | 577.636 | 77.12% | |
| LRP0041312307017 19361 | 25.92 | 52.220 | 14.280 | 43.393 | 13.357 | 579.596 | 77.73% | |
| LRP0041312307017 19337 | 25.5 | 52.164 | 14.284 | 43.306 | 13.346 | 577.966 | 77.57% | |
| LRP0041312307017 24472 | 25.5 | 52.151 | 14.324 | 43.307 | 13.335 | 577.490 | 77.31% | |
| LRP0041312307017 19336 | 25.5 | 52.210 | 14.279 | 43.393 | 13.360 | 579.727 | 77.77% | |
| LRP0041312307017 19338 | 25.58 | 52.144 | 14.316 | 43.350 | 13.325 | 577.617 | 77.38% | |
| LRP0041312307017 19364 | 25.64 | 52.200 | 14.302 | 43.392 | 13.366 | 579.992 | 77.69% | |
| LRP0041312307017 19339 | 25.72 | 52.109 | 14.311 | 43.264 | 13.327 | 576.582 | 77.32% | |
| LRP0041312307017 19342 | 25.76 | 52.178 | 14.274 | 43.350 | 13.344 | 578.473 | 77.67% | |
| LRP0041312307017 24425 | 25.74 | 52.020 | 14.364 | 43.134 | 13.358 | 576.204 | 77.11% | |
| LRP0041312307017 19325 | 25.62 | 52.238 | 14.329 | 43.310 | 13.325 | 577.123 | 77.10% | |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 10 of 50

Non-negotiable

| 0 | 94 | | | |
|----|----|----|----|--|
| - | 5 | 70 | 1 | |
| W. | J | Ш | €Ľ | |


| LRP0041312307017 19316 | 25.56 | 52.149 | 14.330 | 43.350 | 13.333 | 577.972 | 77.34% |
|---------------------------|-------|--------|--------|--------|--------|---------|--------|
| LRP0041312307017 19327 | 25.54 | 52.153 | 14.347 | 43.350 | 13.314 | 577.156 | 77.13% |
| LRP0041312307017 24491 | 25.54 | 52.114 | 14.347 | 43.307 | 13.350 | 578.124 | 77.32% |
| LRP0041312307017 24524 | 25.54 | 52.186 | 14.315 | 43.393 | 13.332 | 578.509 | 77.44% |
| LRP0041312307017 19308 | 25.56 | 52.102 | 14.311 | 43.297 | 13.376 | 579.128 | 77.67% |
| LRP0041312307017 19333 | 25.62 | 52.196 | 14.317 | 43.393 | 13.351 | 579.329 | 77.52% |
| LRP0041312307017 24403 | 25.64 | 52.154 | 14.284 | 43.339 | 13.295 | 576.182 | 77.34% |
| LRP0041312307017 24401 | 25.6 | 52.169 | 14.372 | 43.349 | 13.335 | 578.056 | 77.10% |
| LRP0041312307017 24399 | 25.4 | 52.147 | 14.286 | 43.264 | 13.333 | 576.851 | 77.43% |
| LRP0041312307017 24490 | 25.44 | 52.231 | 14.281 | 43.480 | 13.319 | 579.086 | 77.63% |
| LRP0041312307017 24546 | 25.56 | 52.171 | 14.354 | 43.350 | 13.331 | 577.915 | 77.17% |
| LRP0041312307017 24395 | 25.7 | 52.161 | 14.340 | 43.349 | 13.339 | 578.236 | 77.31% |
| LRP0041312307017 19331 | 25.6 | 52.206 | 14.313 | 43.393 | 13.346 | 579.117 | 77.50% |
| LRP0041312307017 19330 | 25.6 | 52.240 | 14.264 | 43.436 | 13.351 | 579.892 | 77.82% |
| LRP0041312307017 19329 | 25.5 | 52.182 | 14.327 | 43.392 | 13.352 | 579.371 | 77.50% |
| LRP0041312307017 19315 | 25.54 | 52.170 | 14.279 | 43.350 | 13.344 | 578.473 | 77.65% |
| LRP0041312307017 24492 | 25.54 | 52.188 | 14.307 | 43.350 | 13.360 | 579.149 | 77.57% |
| LRP0041312307017 24466 | 25.52 | 52.152 | 14.319 | 43.306 | 13.335 | 577.503 | 77.34% |
| LRP0041312307017 24486 | 25.5 | 52.189 | 14.203 | 43.382 | 13.292 | 576.625 | 77.79% |
| Remarks | | | | No | | | |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 11 of 50

Non-negotiable



Note:

The result of maximum power determination was satisfactory.

8. Insulation test

- 8.1 Reference documents:IEC61215-2:2016
- 8.2. Sample size: ISO 2859-1 at the sample plan of General inspection S-1, Sample size 5pcs, AQL

According to the requirement, SGS inspector performedinsulation test for the randomly chosen 5pcs of PV modules.

Details as Follows:


| Items name | Insulation test | | | | | | | |
|---------------------------|---|--|---------------------|--------------------------------|--------|--|--|--|
| Technical requirement | IEC61215-2:2016 Terrestrial photovoltaic (PV) modules – Design qualification and type approval –Part 2: Test procedures MQT03Insulation test: a) No dielectric breakdown or surface tracking during 4.3.4 c). b) For modules with an area of less than 0,1 m² the insulation resistance shall not be lessthan 400 MΩ. c) For modules with an area larger than 0,1 m² the measured insulation resistance times thearea of the module shall not be less than 40 MΩ·m². | | | | | | | |
| Test time | Aug.21, 2023 | | | | | | | |
| Environmental information | TEMP(℃) 24.6 Humidity (%) | | | 68 | | | | |
| | Withs | stand voltage | | Insulation | | | | |
| Sample No. | Test voltage (V) | Whether there is breakdown or surface fracture | Test voltage (V) | Resistance value (G Ω) | Result | | | |
| LRP0041312307017 21417 | 4800 No | | 1500 | 5.67GΩ | Pass | | | |
| LRP0041312307017 24475 | 4800 | No | 1500 | 4.54GΩ | Pass | | | |
| LRP0041312307017 19343 | 4800 | No | 1500 | 5.55GΩ | Pass | | | |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 12 of 50

Non-negotiable



| LRP0041312307017 | 4800 | No | 1500 | 4.56GO | Pass | |
|------------------|---|-----|------|---------|------|--|
| 19361 | 4600 | INO | 1500 | 4.56612 | rass | |
| LRP0041312307017 | 4800 | No | 4500 | 6.7700 | Door | |
| 19337 | 4000 | INO | 1500 | 6.77GΩ | Pass | |
| Remarks | The module area is $2.583 m^2$, and the measured resistance shall be \geqslant 15.48M Ω | | | | | |

Note:

The result of insulation test was satisfactory.

Continuity test of equipotential bonding

- 9.1 Reference documents:IEC61730-2:2016
- 9.2. Sample size: ISO 2859-1 at the sample plan of General inspection S-1, Sample size 5pcs, AQL 0.

According to the requirement, SGS inspector performed continuity test of equipotential bonding for the randomly chosen 5pcs of PV modules.

Details as Follows:


| Items name | Continuity test of equipotential bonding |
|--------------------------|---|
| Technical requirement | IEC61730-2:2016 Photovoltaic (PV) module safety qualification –Part 2: Requirements for testing MST 13 Continuity test of equipotential bonding: The purpose of this test is to verify the continuous path between accessible conductive parts that are in direct contact with each other (e.g. parts of a metallic frame). The procedure is as follows: a) Select the manufacturer's designated point for equipotential bonding and the recommended connection. Attach to one terminal of the constant current supply. b) Select an adjacent (connected) exposed conductive component with the greatest physical displacement from the grounding point and attach to the other terminal of the current supply. c) Attach the voltmeter to the two conductive components attached to the current supply in proximity to the current leads. d) Apply a current 250 % ± 10 % of the maximum overcurrent protection rating of the PV module for a minimum of 2 min. e) Measure the applied current and the resultant voltage drop. f) Reduce the current to zero. g) Repeat for all other accessible conductive parts. h) Repeat the test for all connection(s), terminal(s), and/or wire(s) included or specified |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 13 of 50

Non-negotiable



| | by the manufacturer for grounding the PV module. | | | | | | | |
|---------------------------|--|--|----------|--------------------------|-----------|--|--|--|
| | The | The resistance between the selected exposed conductive component and every other | | | | | | |
| | cond | conductive component of the PV module shall be less than 0,1 Ω . | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| | | | | | | | | |
| Test time | | | | Aug.21, 2023 | | | | |
| Environmental | TF | MP (℃) | 24.6 | Humidity (%) | 68 | | | |
| information | | | 24.0 | Trainialty (707 | | | | |
| Sample No. | No. | Cur | rent (A) | Grounding resistance (mΩ | 2) Result | | | |
| I DD004404007047 | 1 | 62.5 | | 4.34 | | | | |
| LRP0041312307017 21417 | 2 | 62.5 | | 5.54 | Pass | | | |
| 21417 | 3 | 62.5 | | 4.26 | | | | |
| LRP0041312307017 | 1 | | 62.5 | 4.45 | | | | |
| 24475 | 2 | | 62.5 | 4.35 | Pass | | | |
| 24473 | 3 | | 62.5 | 4.65 | | | | |
| I DD0041212207017 | 1 | | 62.5 | 4.34 | | | | |
| LRP0041312307017 19343 | 2 | | 62.5 | 5.12 | Pass | | | |
| 19343 | 3 | | 62.5 | 4.62 | | | | |
| I DD0044242207047 | 1 | | 62.5 | 5.12 | | | | |
| LRP0041312307017 19361 | 2 | | 62.5 | 4.66 | Pass | | | |
| 19301 | 3 | | 62.5 | 4.88 | | | | |
| I DD0044242207047 | 1 | | 62.5 | 4.33 | | | | |
| LRP0041312307017 19337 | 2 | | 62.5 | 5.32 | Pass | | | |
| 19001 | 3 | | 62.5 | 4.53 | | | | |
| Remarks | | | | No | | | | |

Note:

The result of continuity test of equipotential bonding was satisfactory.



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



10. Other items

Other items of IEC61215-2:2016 and IEC61730-2:2016 are not witnessed in thisinspection, but verified by checking the test report and certificate.

IEC_61215_61730_2016 report No.:704061700516-21

IEC_61215_61730_2016 certificate No.:NO.Z2 099333 0045 Rev, 23

Note:

Other items of IEC61215-2:2016 include clauses 4.4 to 4.19; Other items of IEC61730-2:2016 include clauses 10.3,10.5-10.10,10.12,10.14-10.33.

11. Product ID for this batch


| Mono Sol | ar Module | LR5-72HTH-575M | | | |
|---------------|---------------|----------------|---------------|---------------|--|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01707005 | 01716929 | 01716081 | 01716617 | 01722648 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01706977 | 01716828 | 01716039 | 01716731 | 01722666 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01706968 | 01717012 | 01716105 | 01716677 | 01722583 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01706948 | 01716970 | 01716094 | 01716770 | 01722642 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01706959 | 01716977 | 01716078 | 01716767 | 01722659 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01707002 | 01716972 | 01716016 | 01716779 | 01722589 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01706941 | 01716909 | 01716106 | 01716781 | 01722646 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01707016 | 01716907 | 01716074 | 01716631 | 01722599 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01706922 | 01717014 | 01716051 | 01716728 | 01722597 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01706929 | 01716920 | 01716028 | 01716745 | 01722680 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01706984 | 01717034 | 01716052 | 01716768 | 01722610 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 15 of 50

Non-negotiable

| 1 | 0.4 | P | 1 | |
|------|-------|-----|----------|---|
| 6 | - | 100 | 6 | _ |
| III. | ЭU | | E | 3 |
| 4000 | Sh. A | | Name of | |


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| 01706927 | 01716964 | 01716050 | 01716785 | 01722661 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706937 | 01716988 | 01716077 | 01716772 | 01722601 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706928 | 01717001 | 01716064 | 01716695 | 01722678 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706970 | 01716918 | 01716084 | 01716763 | 01722676 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706985 | 01717019 | 01716110 | 01716759 | 01722675 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706981 | 01716906 | 01716108 | 01716761 | 01722621 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706982 | 01716995 | 01716115 | 01716758 | 01722604 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706987 | 01717016 | 01716116 | 01716704 | 01722588 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706933 | 01716914 | 01716065 | 01716766 | 01722633 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706944 | 01716969 | 01716079 | 01716760 | 01722574 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706946 | 01716921 | 01716091 | 01716750 | 01722579 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706943 | 01716900 | 01716102 | 01716755 | 01722569 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706938 | 01716902 | 01716054 | 01716744 | 01722520 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706954 | 01716901 | 01716129 | 01716787 | 01722602 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706952 | 01716919 | 01716124 | 01716671 | 01722573 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706932 | 01717079 | 01716142 | 01716380 | 01722622 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01702743 | 01717104 | 01716128 | 01716687 | 01722603 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01702739 | 01717116 | 01716121 | 01716747 | 01722615 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 16 of 50

Non-negotiable




| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706924 | 01718218 | 01716141 | 01716751 | 01722619 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01702864 | 01718219 | 01716045 | 01716632 | 01722614 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706557 | 01717085 | 01716132 | 01716674 | 01722606 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01704055 | 01717032 | 01716146 | 01716649 | 01722650 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01704209 | 01717062 | 01716086 | 01716722 | 01722576 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707868 | 01717088 | 01716122 | 01716783 | 01722585 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707631 | 01717241 | 01716047 | 01716675 | 01722644 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01702752 | 01715292 | 01718146 | 01720372 | 01718661 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01703463 | 01715274 | 01718119 | 01720406 | 01718919 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01700911 | 01713996 | 01717966 | 01720348 | 01718884 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01708378 | 01715166 | 01718272 | 01720426 | 01718056 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01702681 | 01715277 | 01718153 | 01720424 | 01718053 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01708276 | 01715238 | 01718136 | 01720430 | 01718686 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707607 | 01715265 | 01718156 | 01720432 | 01718817 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01708318 | 01715276 | 01718172 | 01720280 | 01718857 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01708271 | 01715245 | 01717141 | 01720361 | 01718710 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706964 | 01715280 | 01717101 | 01720405 | 01718812 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01708170 | 01714026 | 01716800 | 01720385 | 01716044 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 17 of 50

Non-negotiable


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01708158 | 01715261 | 01715121 | 01720422 | 01717685 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01708209 | 01715275 | 01716816 | 01720415 | 01717763 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01708230 | 01715251 | 01716803 | 01720413 | 01716837 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707106 | 01715286 | 01715153 | 01720396 | 01717764 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707067 | 01713934 | 01716808 | 01720306 | 01718034 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707096 | 01715281 | 01718033 | 01720408 | 01718039 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707025 | 01715248 | 01718118 | 01720418 | 01718052 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707030 | 01715202 | 01718092 | 01720433 | 01718054 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707079 | 01715273 | 01718124 | 01720428 | 01717991 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707118 | 01715241 | 01718127 | 01720279 | 01720048 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707071 | 01713997 | 01718023 | 01720400 | 01717914 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707062 | 01715267 | 01718099 | 01720388 | 01720057 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706991 | 01715271 | 01718096 | 01720404 | 01720630 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706965 | 01715231 | 01718095 | 01720401 | 01720483 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707024 | 01715264 | 01718112 | 01720429 | 01720514 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706992 | 01713992 | 01718090 | 01720369 | 01718728 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706997 | 01715278 | 01718097 | 01720420 | 01718691 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706976 | 01715266 | 01718094 | 01720390 | 01718729 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 18 of 50

Non-negotiable




| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707100 | 01715225 | 01718128 | 01720436 | 01718704 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706962 | 01715206 | 01718089 | 01720403 | 01718705 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706980 | 01715227 | 01717984 | 01720317 | 01718922 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706951 | 01715228 | 01718248 | 01720409 | 01718905 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01707013 | 01715188 | 01718104 | 01720326 | 01718916 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706999 | 01715234 | 01717977 | 01720377 | 01718888 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01706994 | 01715220 | 01718114 | 01720410 | 01718891 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710777 | 01715208 | 01718337 | 01720315 | 01718703 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711113 | 01715294 | 01718326 | 01720461 | 01718869 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711177 | 01715301 | 01718313 | 01720468 | 01718876 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711075 | 01715299 | 01718324 | 01720471 | 01718708 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711131 | 01715253 | 01718316 | 01720465 | 01718643 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711153 | 01715291 | 01718321 | 01720423 | 01718675 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711149 | 01715297 | 01718329 | 01720457 | 01718851 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711137 | 01715300 | 01718333 | 01717688 | 01718871 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711099 | 01715327 | 01718332 | 01720259 | 01718909 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711098 | 01715326 | 01718339 | 01720435 | 01718903 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711120 | 01715262 | 01718353 | 01720442 | 01718822 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 19 of 50

Non-negotiable

| 0 | 70 | 7 | M | |
|-------|-----|----|------|--|
| - 9 | 51 | 1. | 9: | |
| - | 301 | l٦ | 1=1 | |
| - All | - W | | 1.40 | |


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711077 | 01713921 | 01718341 | 01720443 | 01722477 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710951 | 01715333 | 01718359 | 01720427 | 01722451 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711034 | 01715288 | 01718338 | 01720445 | 01721845 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01709040 | 01714061 | 01718331 | 01720278 | 01721674 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711102 | 01715320 | 01718346 | 01720452 | 01715884 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711236 | 01715318 | 01718340 | 01720419 | 01715863 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711231 | 01715316 | 01718322 | 01720456 | 01715435 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711227 | 01715321 | 01718297 | 01720454 | 01718894 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711151 | 01714474 | 01718343 | 01720458 | 01718877 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711241 | 01715308 | 01718336 | 01720463 | 01718956 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01708922 | 01714455 | 01718344 | 01720459 | 01718886 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01708733 | 01715282 | 01718345 | 01720464 | 01718840 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01709020 | 01715283 | 01718367 | 01720441 | 01718850 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01709018 | 01714070 | 01718362 | 01720440 | 01718870 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01709010 | 01715268 | 01718349 | 01720438 | 01718854 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01709114 | 01715270 | 01718350 | 01720450 | 01718866 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711190 | 01715313 | 01718360 | 01720462 | 01718864 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711166 | 01715210 | 01718354 | 01720495 | 01718692 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 20 of 50

Non-negotiable

| 1 | 0.4 | P | 1 | |
|------|-------|-----|----------|---|
| 6 | - | 100 | 6 | _ |
| III. | ЭU | | E | 3 |
| 4000 | Sh. A | | Name of | |


| Mono Sola | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711168 | 01715259 | 01718356 | 01720496 | 01718782 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710673 | 01715285 | 01718310 | 01720501 | 01718707 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711182 | 01715246 | 01718291 | 01720500 | 01718689 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710868 | 01715240 | 01718292 | 01720481 | 01718858 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711163 | 01715303 | 01718377 | 01720494 | 01718809 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711183 | 01715213 | 01718293 | 01720484 | 01718815 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711142 | 01715258 | 01718390 | 01720469 | 01718759 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711054 | 01717198 | 01718171 | 01716703 | 01722763 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711242 | 01717280 | 01718170 | 01716653 | 01722568 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711219 | 01717288 | 01718166 | 01716626 | 01722752 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711238 | 01717295 | 01718143 | 01716696 | 01722754 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711157 | 01717282 | 01718180 | 01716620 | 01722670 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711218 | 01717290 | 01718279 | 01716710 | 01722702 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711173 | 01715027 | 01718178 | 01716639 | 01722753 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711243 | 01715017 | 01717004 | 01716756 | 01722762 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711133 | 01714724 | 01718280 | 01716705 | 01722776 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711256 | 01712539 | 01718275 | 01718413 | 01722611 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711148 | 01714880 | 01718151 | 01716622 | 01722757 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 21 of 50

Non-negotiable

| 0 | | |
|---|---|--|
| | 4 | |
| U | | |


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711152 | 01714714 | 01718137 | 01716701 | 01722699 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711154 | 01713897 | 01718187 | 01716688 | 01722792 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711159 | 01713049 | 01718173 | 01718414 | 01722707 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711104 | 01710979 | 01718131 | 01718416 | 01722684 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711160 | 01713347 | 01718167 | 01716726 | 01722718 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711274 | 01713115 | 01718168 | 01716769 | 01722720 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711302 | 01713124 | 01718162 | 01716717 | 01722739 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711239 | 01710259 | 01718177 | 01716709 | 01722745 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711278 | 01717218 | 01718253 | 01716636 | 01722734 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711249 | 01718226 | 01718159 | 01716662 | 01722695 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711298 | 01717189 | 01718164 | 01716637 | 01722671 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711235 | 01718224 | 01718255 | 01716780 | 01722667 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711291 | 01717255 | 01718182 | 01716746 | 01722645 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711246 | 01717253 | 01718188 | 01716736 | 01722706 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711244 | 01717270 | 01718257 | 01716693 | 01722639 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711289 | 01717263 | 01718169 | 01716748 | 01722652 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711316 | 01717279 | 01717924 | 01716691 | 01722668 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711304 | 01717023 | 01718266 | 01716692 | 01722651 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 22 of 50

Non-negotiable

| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711309 | 01717247 | 01718256 | 01716698 | 01722674 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711308 | 01717246 | 01718271 | 01716753 | 01722689 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711306 | 01717243 | 01718247 | 01716699 | 01722697 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711327 | 01717244 | 01718138 | 01716689 | 01722562 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711230 | 01717267 | 01718147 | 01716764 | 01722688 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711340 | 01717228 | 01718269 | 01716762 | 01722710 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01711328 | 01717227 | 01718126 | 01716754 | 01722669 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710017 | 01713068 | 01718348 | 01716659 | 01720790 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710027 | 01713071 | 01718361 | 01718433 | 01720984 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710028 | 01713065 | 01718351 | 01718417 | 01720976 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710020 | 01713085 | 01718370 | 01718415 | 01720973 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710030 | 01713052 | 01718368 | 01718424 | 01720952 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710025 | 01713054 | 01718355 | 01716697 | 01720961 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710011 | 01713070 | 01718376 | 01718438 | 01721090 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710015 | 01713086 | 01718358 | 01718440 | 01720962 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710029 | 01713069 | 01718391 | 01716629 | 01720974 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710024 | 01713100 | 01718399 | 01718421 | 01720935 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| | ı | 1 | ī | ī |

01718385



01710056

01713073

01718446


The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND

> www.sgsgroup.com.cn e sgs.china@sgs.com

01720995



Page 23 of 50

Non-negotiable

| 4 | 70 | 7 | M | |
|------|-----|----------|-----|---|
| - 9 | | 12 | 9: | |
| - | 791 | lΥ | I=1 | 7 |
| - 40 | - W | <u> </u> | 100 | 9 |


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710041 | 01717386 | 01718387 | 01716720 | 01720996 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710054 | 01713088 | 01718398 | 01718428 | 01720862 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710043 | 01713081 | 01718378 | 01716719 | 01720852 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710046 | 01712896 | 01718364 | 01718425 | 01720924 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710048 | 01713072 | 01718303 | 01716706 | 01720998 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710042 | 01712971 | 01718306 | 01716716 | 01720991 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710055 | 01713082 | 01718315 | 01718448 | 01720956 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710052 | 01713114 | 01718317 | 01718436 | 01720951 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710033 | 01713121 | 01718318 | 01718455 | 01720964 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710037 | 01714193 | 01718386 | 01718453 | 01720797 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710045 | 01714097 | 01718308 | 01718430 | 01720970 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710088 | 01711500 | 01720039 | 01718461 | 01720972 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710063 | 01711485 | 01718410 | 01716718 | 01720979 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710064 | 01711486 | 01718380 | 01716714 | 01720957 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710075 | 01711237 | 01718412 | 01716713 | 01720913 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710078 | 01714258 | 01720038 | 01718449 | 01720782 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710061 | 01714210 | 01718408 | 01716700 | 01720999 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710070 | 01714225 | 01718301 | 01716657 | 01720988 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 24 of 50

Non-negotiable




| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710032 | 01714169 | 01720042 | 01716605 | 01720842 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710036 | 01714207 | 01720041 | 01716665 | 01720982 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710051 | 01714101 | 01720043 | 01716663 | 01720989 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710057 | 01714238 | 01718342 | 01716707 | 01721026 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710053 | 01714259 | 01718296 | 01716702 | 01721025 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710059 | 01714278 | 01718384 | 01716619 | 01721006 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710021 | 01714217 | 01718311 | 01718423 | 01720955 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710175 | 01717147 | 01717833 | 01720524 | 01716567 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710181 | 01717169 | 01717719 | 01720515 | 01718978 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710182 | 01717154 | 01717776 | 01720522 | 01718950 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710108 | 01716974 | 01717572 | 01720479 | 01718881 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710183 | 01718227 | 01717477 | 01720505 | 01718947 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710172 | 01718223 | 01713370 | 01720509 | 01718908 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710156 | 01717164 | 01716255 | 01720486 | 01718914 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01709430 | 01717187 | 01716256 | 01720510 | 01718933 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710171 | 01717158 | 01716217 | 01720507 | 01718935 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710159 | 01717163 | 01716247 | 01715009 | 01716574 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710102 | 01718225 | 01716257 | 01720558 | 01718958 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 25 of 50

Non-negotiable

| | 0 | 0 | |
|---|-----|---|---|
| - | l v | | |
| | | ~ | _ |


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710157 | 01716924 | 01716253 | 01720508 | 01718625 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710160 | 01716926 | 01716243 | 01720560 | 01718594 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710164 | 01716915 | 01716267 | 01720490 | 01718918 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710147 | 01716903 | 01717711 | 01720472 | 01718923 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710194 | 01716885 | 01716265 | 01720527 | 01718915 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710204 | 01716810 | 01716271 | 01720512 | 01718938 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710197 | 01716838 | 01716264 | 01715003 | 01718954 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710176 | 01716863 | 01716140 | 01720506 | 01718679 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710205 | 01716813 | 01716218 | 01720503 | 01718913 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710180 | 01716796 | 01716314 | 01720521 | 01718965 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710190 | 01716788 | 01716234 | 01720499 | 01718842 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710189 | 01716811 | 01716213 | 01720487 | 01718943 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710170 | 01716798 | 01716238 | 01720482 | 01716577 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710185 | 01715102 | 01716205 | 01720493 | 01718969 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710167 | 01714803 | 01716229 | 01720488 | 01718931 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710169 | 01714488 | 01716226 | 01720564 | 01718962 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710207 | 01713625 | 01716219 | 01720553 | 01718959 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710214 | 01716930 | 01716233 | 01720566 | 01718937 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 26 of 50

Non-negotiable




| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710151 | 01715112 | 01716236 | 01720567 | 01718968 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710218 | 01715008 | 01716250 | 01714992 | 01718952 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710203 | 01715053 | 01716222 | 01720538 | 01718946 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710206 | 01715060 | 01716237 | 01720562 | 01718906 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01709746 | 01717145 | 01716328 | 01715007 | 01722499 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710113 | 01715475 | 01716183 | 01720513 | 01722539 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710087 | 01715397 | 01715644 | 01720485 | 01722535 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713078 | 01715445 | 01718411 | 01716535 | 01716568 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714279 | 01715428 | 01718389 | 01716520 | 01716571 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714214 | 01715448 | 01720040 | 01716612 | 01718998 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714309 | 01715391 | 01718395 | 01716715 | 01718966 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714216 | 01713918 | 01718393 | 01716490 | 01718995 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714219 | 01715376 | 01718397 | 01716538 | 01718880 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712496 | 01715377 | 01720056 | 01716533 | 01718991 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712608 | 01715398 | 01718388 | 01716531 | 01718660 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712577 | 01715453 | 01720047 | 01716595 | 01718924 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712594 | 01710005 | 01718383 | 01716536 | 01718970 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712464 | 01715388 | 01720054 | 01716518 | 01716570 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 27 of 50

Non-negotiable

| - | 00 | 70 | | |
|----|----|----|---|--|
| - | 51 | 7 | 6 | |
| E. | | 4 | u | |


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712722 | 01715423 | 01718403 | 01716111 | 01718882 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712704 | 01715384 | 01718404 | 01716126 | 01718990 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712645 | 01715450 | 01720051 | 01716476 | 01718945 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714187 | 01715440 | 01720075 | 01716463 | 01718979 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714304 | 01715472 | 01720063 | 01716138 | 01718694 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712855 | 01713902 | 01718160 | 01716496 | 01718939 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712804 | 01715401 | 01720072 | 01716506 | 01716572 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712829 | 01715479 | 01717864 | 01716360 | 01718955 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712840 | 01715487 | 01720070 | 01716333 | 01719017 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712835 | 01715459 | 01717906 | 01716510 | 01719034 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712834 | 01715482 | 01720081 | 01716491 | 01718957 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712825 | 01715485 | 01720071 | 01716512 | 01716576 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712833 | 01715477 | 01718298 | 01716513 | 01719015 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710168 | 01715486 | 01720083 | 01716509 | 01719011 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712538 | 01715488 | 01717882 | 01716511 | 01719013 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712830 | 01715478 | 01720080 | 01716527 | 01718953 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712822 | 01715389 | 01720046 | 01716514 | 01719000 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712847 | 01715517 | 01720053 | 01716394 | 01718983 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 28 of 50

Non-negotiable




| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712820 | 01715495 | 01717544 | 01716260 | 01718961 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712836 | 01715496 | 01718402 | 01716103 | 01719014 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714298 | 01715480 | 01720076 | 01716507 | 01718982 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714340 | 01715533 | 01720059 | 01716503 | 01718984 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714341 | 01715481 | 01718371 | 01716532 | 01719002 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713048 | 01715492 | 01718299 | 01716583 | 01719007 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712975 | 01715416 | 01718407 | 01716525 | 01719009 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714742 | 01715695 | 01720049 | 01720528 | 01721024 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712850 | 01715692 | 01720077 | 01720511 | 01720985 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712831 | 01715665 | 01718320 | 01720542 | 01721020 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712792 | 01715658 | 01718382 | 01720545 | 01720975 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712813 | 01715699 | 01720044 | 01720519 | 01720992 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712802 | 01715673 | 01718409 | 01720529 | 01721021 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713030 | 01715697 | 01718375 | 01720531 | 01721042 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714728 | 01713932 | 01718401 | 01720474 | 01721037 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714705 | 01715528 | 01720119 | 01720466 | 01721014 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714712 | 01715524 | 01720095 | 01720554 | 01721008 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714610 | 01715468 | 01720069 | 01714999 | 01721010 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 29 of 50

Non-negotiable


| Mono Sol | ar Module | LR5-72HTH-575M | | |
|---------------|---------------|----------------|---------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714673 | 01715455 | 01720097 | 01720478 | 01721003 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714734 | 01715540 | 01720106 | 01720548 | 01721011 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712912 | 01715573 | 01721889 | 01720537 | 01720910 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714735 | 01715584 | 01720074 | 01714996 | 01721053 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714413 | 01715497 | 01720079 | 01714974 | 01721036 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714752 | 01713924 | 01720087 | 01720535 | 01721007 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714740 | 01715588 | 01721887 | 01720504 | 01721047 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714771 | 01715593 | 01720099 | 01720492 | 01721039 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714753 | 01715590 | 01717859 | 01720497 | 01721041 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714756 | 01715600 | 01720111 | 01720516 | 01721009 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714763 | 01715586 | 01720108 | 01720520 | 01720968 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714744 | 01715604 | 01720102 | 01720518 | 01721086 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714680 | 01715619 | 01720121 | 01720480 | 01721043 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714773 | 01713957 | 01721890 | 01720517 | 01721078 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714758 | 01713922 | 01720105 | 01720168 | 01721100 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714762 | 01715565 | 01720113 | 01720551 | 01721101 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713592 | 01715587 | 01720107 | 01720540 | 01721091 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714769 | 01715598 | 01720109 | 01720556 | 01721084 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 30 of 50

Non-negotiable




| Mono Solar Module | | LR5-72HTH-575M | | | |
|-------------------|---------------|----------------|---------------|---------------|--|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01714807 | 01713923 | 01720118 | 01720557 | 01721030 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01714822 | 01715625 | 01720088 | 01720533 | 01721031 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01714806 | 01715675 | 01720120 | 01720541 | 01721018 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01714767 | 01715686 | 01720115 | 01720525 | 01721032 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01714768 | 01715667 | 01717933 | 01720539 | 01720730 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713758 | 01715543 | 01720092 | 01720550 | 01721034 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01714783 | 01715507 | 01720093 | 01720532 | 01721035 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713209 | 01701457 | 01716366 | 01716666 | 01722843 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713272 | 01701468 | 01716202 | 01716667 | 01722861 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713308 | 01701534 | 01716306 | 01716517 | 01722780 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713244 | 01701537 | 01713578 | 01716711 | 01722809 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713157 | 01701446 | 01717875 | 01718431 | 01722868 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713332 | 01701769 | 01717890 | 01718435 | 01722855 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713236 | 01701954 | 01710460 | 01716786 | 01722850 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713326 | 01701973 | 01717993 | 01718437 | 01722846 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713186 | 01701966 | 01716266 | 01718465 | 01722841 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713324 | 01701476 | 01716275 | 01718442 | 01722803 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713173 | 01701992 | 01716199 | 01716784 | 01722798 | |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 31 of 50

Non-negotiable

| 0 | 70 | 7 | 1 | |
|-----|-------|-------|------|---|
| - 6 | 5 | | | 7 |
| _ | 9 | 1 4 | | |
| W. | -## V | الساة | I W. | |


| Mono Solar Module | | LR5-72HTH-575M | | |
|-------------------|---------------|----------------|---------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713241 | 01702085 | 01716263 | 01716777 | 01722795 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710250 | 01701472 | 01716273 | 01718439 | 01722828 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713238 | 01702094 | 01716309 | 01718429 | 01722818 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713183 | 01703444 | 01716289 | 01718462 | 01722825 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713280 | 01701460 | 01716346 | 01716690 | 01722756 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713289 | 01703570 | 01716279 | 01716775 | 01722822 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01710101 | 01703619 | 01716368 | 01716638 | 01722769 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713294 | 01717716 | 01716239 | 01718459 | 01722794 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713194 | 01717723 | 01716303 | 01716678 | 01722774 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713281 | 01717790 | 01716307 | 01718488 | 01722786 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713287 | 01717698 | 01716301 | 01716669 | 01722556 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713282 | 01716793 | 01716254 | 01718458 | 01722773 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713253 | 01717819 | 01716231 | 01716676 | 01722768 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713286 | 01717706 | 01716302 | 01716680 | 01722784 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713296 | 01717701 | 01716130 | 01716765 | 01722729 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713284 | 01717728 | 01716339 | 01718483 | 01722802 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713187 | 01717814 | 01716338 | 01716771 | 01722612 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713315 | 01717741 | 01716101 | 01718467 | 01722806 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 32 of 50

Non-negotiable




| Mono Solar Module | | LR5-72HTH-575M | | | |
|-------------------|---------------|----------------|---------------|---------------|--|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713283 | 01717817 | 01716304 | 01718479 | 01722725 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713243 | 01717799 | 01716294 | 01718495 | 01722805 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713285 | 01717821 | 01716287 | 01718422 | 01722714 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713276 | 01717822 | 01716353 | 01718470 | 01722767 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713269 | 01717795 | 01716297 | 01718468 | 01722726 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01710198 | 01701517 | 01716298 | 01716664 | 01722727 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713293 | 01703347 | 01716270 | 01718457 | 01722820 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713170 | 01715641 | 01720142 | 01714654 | 01721075 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713312 | 01715743 | 01720128 | 01714329 | 01720777 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713261 | 01715768 | 01718369 | 01714722 | 01721051 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713222 | 01715763 | 01720217 | 01718506 | 01721000 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713232 | 01709942 | 01720194 | 01716740 | 01721074 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713221 | 01715770 | 01720167 | 01718508 | 01721029 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713235 | 01715727 | 01720197 | 01718511 | 01721126 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713179 | 01715715 | 01720198 | 01718512 | 01721148 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713184 | 01715755 | 01718357 | 01716556 | 01721151 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713182 | 01715733 | 01720150 | 01716557 | 01721132 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713298 | 01715751 | 01720091 | 01718496 | 01721135 | |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 33 of 50

Non-negotiable




| Mono Solar Module | | LR5-72HTH-575M | | | |
|-------------------|---------------|----------------|---------------|---------------|--|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713310 | 01715710 | 01720206 | 01718509 | 01721144 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713111 | 01715736 | 01720199 | 01718469 | 01721054 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713577 | 01715620 | 01720202 | 01718533 | 01721071 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713579 | 01715635 | 01720094 | 01718505 | 01721063 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713586 | 01715756 | 01720207 | 01718492 | 01721019 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713590 | 01715758 | 01720208 | 01716561 | 01721048 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713663 | 01715629 | 01720158 | 01718490 | 01721052 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713580 | 01715661 | 01720200 | 01718454 | 01721070 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713180 | 01715678 | 01720181 | 01716712 | 01721080 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713168 | 01715647 | 01720159 | 01718493 | 01721016 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713249 | 01715717 | 01720249 | 01718519 | 01721001 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713311 | 01715706 | 01720239 | 01718427 | 01721081 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713538 | 01715757 | 01718300 | 01718451 | 01721089 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713558 | 01715759 | 01720210 | 01718475 | 01721087 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713359 | 01715739 | 01720222 | 01718464 | 01721057 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713540 | 01715724 | 01720211 | 01718420 | 01721108 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713565 | 01715690 | 01720130 | 01718477 | 01721061 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713572 | 01715704 | 01720215 | 01718463 | 01721065 | |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 34 of 50

Non-negotiable




| Mono Solar Module | | LR5-72HTH-575M | | | |
|-------------------|---------------|----------------|---------------|---------------|--|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713561 | 01715597 | 01720176 | 01717885 | 01721062 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713360 | 01715653 | 01720234 | 01716984 | 01721028 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713556 | 01715711 | 01720220 | 01718161 | 01721027 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713344 | 01715720 | 01720129 | 01718394 | 01721056 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713288 | 01715671 | 01720216 | 01718396 | 01720781 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713354 | 01715687 | 01720179 | 01720318 | 01721068 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713328 | 01715684 | 01718278 | 01720310 | 01721066 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713320 | 01717729 | 01716415 | 01718646 | 01721085 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713275 | 01717801 | 01716406 | 01718726 | 01721073 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713329 | 01717783 | 01716379 | 01718718 | 01721045 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713323 | 01717796 | 01716343 | 01718697 | 01721002 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713335 | 01717802 | 01716391 | 01712453 | 01721079 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713327 | 01717788 | 01716430 | 01714221 | 01721093 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713321 | 01717756 | 01716390 | 01720587 | 01721105 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713356 | 01717700 | 01716440 | 01720498 | 01721119 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713331 | 01717748 | 01716446 | 01720476 | 01721118 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713330 | 01717687 | 01716393 | 01713998 | 01721114 | |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | |
| 01713367 | 01717703 | 01716356 | 01713854 | 01721060 | |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 35 of 50

Non-negotiable




| Mono Solar Module | | LR5-72HTH-575M | | |
|-------------------|---------------|----------------|---------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713334 | 01717826 | 01716342 | 01713159 | 01721110 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713381 | 01717692 | 01716371 | 01712508 | 01721109 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713390 | 01717854 | 01716225 | 01713166 | 01721104 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713322 | 01717726 | 01716447 | 01712602 | 01721099 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713345 | 01717844 | 01716400 | 01715187 | 01721106 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713314 | 01717732 | 01716372 | 01715626 | 01721123 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713373 | 01717730 | 01716362 | 01715269 | 01721111 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713307 | 01717848 | 01716374 | 01712477 | 01721040 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713349 | 01717807 | 01716378 | 01718735 | 01720993 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713346 | 01717758 | 01716411 | 01718540 | 01721129 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713318 | 01717851 | 01716471 | 01718656 | 01721076 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713046 | 01717850 | 01716409 | 01718709 | 01721098 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713376 | 01717830 | 01716431 | 01718669 | 01721103 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713351 | 01717715 | 01716421 | 01718688 | 01721128 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713340 | 01717835 | 01716526 | 01718753 | 01721046 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713352 | 01717779 | 01716493 | 01718597 | 01721069 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713337 | 01717824 | 01716357 | 01718750 | 01720771 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713371 | 01717782 | 01716375 | 01718730 | 01721120 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 36 of 50

Non-negotiable




| Mono Solar Module | | LR5-72HTH-575M | | |
|-------------------|---------------|----------------|---------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713405 | 01717784 | 01716515 | 01718667 | 01721102 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713364 | 01717808 | 01716209 | 01718607 | 01721049 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713388 | 01716818 | 01716193 | 01718741 | 01721050 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713366 | 01717823 | 01716485 | 01718598 | 01721131 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713380 | 01717852 | 01716092 | 01718713 | 01721150 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713389 | 01717702 | 01716386 | 01716648 | 01720772 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713363 | 01717806 | 01716370 | 01718609 | 01721072 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713427 | 01714036 | 01718352 | 01718818 | 01721191 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713424 | 01715239 | 01720050 | 01718744 | 01721175 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713418 | 01715332 | 01720212 | 01718723 | 01721188 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713414 | 01715347 | 01720261 | 01718722 | 01721187 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713374 | 01715356 | 01720268 | 01718824 | 01721182 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713413 | 01713950 | 01720265 | 01718828 | 01721185 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713423 | 01715729 | 01720266 | 01718792 | 01721154 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713440 | 01715796 | 01720156 | 01718757 | 01721044 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713421 | 01715793 | 01720163 | 01718775 | 01721064 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713437 | 01715802 | 01718374 | 01718779 | 01721005 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713428 | 01715777 | 01720157 | 01718805 | 01721092 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 37 of 50

Non-negotiable

| 1 | 1 | | |
|---|-----|----|----|
| | . 0 | | |
| | ls. | | |
| | G | GS | GS |


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713422 | 01709909 | 01718373 | 01718802 | 01721082 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713438 | 01715782 | 01720162 | 01718796 | 01721162 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713386 | 01715784 | 01720154 | 01718786 | 01721095 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713398 | 01715513 | 01720252 | 01718783 | 01721161 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713394 | 01715775 | 01720205 | 01718734 | 01721107 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713384 | 01715773 | 01720237 | 01718756 | 01721134 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713409 | 01715574 | 01720236 | 01718720 | 01721180 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713392 | 01715776 | 01720238 | 01718778 | 01721172 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713395 | 01714044 | 01720264 | 01718690 | 01721146 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713404 | 01714055 | 01720256 | 01718767 | 01721147 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713401 | 01715177 | 01720255 | 01718774 | 01721130 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713406 | 01715680 | 01720235 | 01718773 | 01721138 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713362 | 01715415 | 01720225 | 01718762 | 01721167 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713379 | 01715721 | 01720223 | 01718670 | 01721176 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713420 | 01715523 | 01720203 | 01718715 | 01720925 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713419 | 01715670 | 01720221 | 01716694 | 01721163 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713417 | 01715779 | 01720250 | 01718719 | 01721164 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713372 | 01715787 | 01720233 | 01718695 | 01721004 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 38 of 50

Non-negotiable




| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713369 | 01715561 | 01720219 | 01718737 | 01721055 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713358 | 01715769 | 01720253 | 01718732 | 01721096 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713383 | 01715761 | 01720299 | 01718651 | 01721088 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713391 | 01715783 | 01720300 | 01718434 | 01721077 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713365 | 01715746 | 01720304 | 01718696 | 01721058 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713402 | 01715747 | 01720292 | 01718676 | 01721083 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713361 | 01715748 | 01720104 | 01718649 | 01721170 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712859 | 01715857 | 01720245 | 01722581 | 01721279 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712877 | 01715846 | 01720271 | 01722582 | 01721371 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713745 | 01715449 | 01720230 | 01722613 | 01721387 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712867 | 01715412 | 01720240 | 01722439 | 01721351 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712883 | 01710058 | 01720226 | 01722609 | 01721356 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713057 | 01715413 | 01720274 | 01722580 | 01721331 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713768 | 01715438 | 01720275 | 01722600 | 01721375 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713042 | 01715836 | 01720285 | 01722567 | 01721334 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713093 | 01715837 | 01720284 | 01722536 | 01721342 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712974 | 01715839 | 01720289 | 01722577 | 01721373 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713080 | 01715718 | 01720297 | 01722620 | 01721347 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 39 of 50

Non-negotiable




| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713064 | 01715886 | 01720291 | 01722594 | 01721394 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713779 | 01715883 | 01720287 | 01722590 | 01721395 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712921 | 01715847 | 01720308 | 01722608 | 01721304 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713055 | 01715845 | 01720260 | 01722555 | 01721372 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713083 | 01715862 | 01720288 | 01722564 | 01721320 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713802 | 01715844 | 01720178 | 01722618 | 01721289 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713015 | 01715905 | 01720286 | 01722637 | 01721338 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713709 | 01715903 | 01720277 | 01722623 | 01721341 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713840 | 01715904 | 01720228 | 01722607 | 01721362 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713833 | 01715888 | 01720229 | 01722625 | 01721299 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713720 | 01715902 | 01720243 | 01722595 | 01721365 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713816 | 01715899 | 01720251 | 01722571 | 01721326 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713780 | 01715896 | 01720257 | 01722605 | 01721339 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713792 | 01715864 | 01720262 | 01722586 | 01721337 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713777 | 01715941 | 01720270 | 01722527 | 01721335 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713743 | 01715945 | 01720267 | 01722570 | 01721333 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713678 | 01715951 | 01720246 | 01722587 | 01721244 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713752 | 01715949 | 01720314 | 01722563 | 01721327 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 40 of 50

Non-negotiable

| 1 | 1 | h d | |
|------|---|------|--|
| 6 | | _9 | |
| 10.7 | | II = | |
| W.J | | 80 W | |


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713338 | 01715953 | 01720321 | 01722445 | 01721246 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713767 | 01715934 | 01720311 | 01722592 | 01721324 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713742 | 01715939 | 01720301 | 01722572 | 01721257 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713810 | 01715935 | 01720248 | 01722496 | 01721359 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713803 | 01715957 | 01718392 | 01722578 | 01721278 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713714 | 01715952 | 01720258 | 01722596 | 01721281 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713796 | 01715937 | 01720247 | 01722566 | 01721259 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713762 | 01715992 | 01720342 | 01718780 | 01721368 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713684 | 01715998 | 01720254 | 01718837 | 01721407 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713781 | 01715979 | 01720323 | 01718800 | 01721361 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713700 | 01715991 | 01720307 | 01718785 | 01721419 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713568 | 01715983 | 01720324 | 01718834 | 01721421 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713567 | 01715910 | 01720309 | 01718807 | 01721415 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713759 | 01715993 | 01720313 | 01718820 | 01721165 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713011 | 01715994 | 01720295 | 01718823 | 01721380 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713824 | 01715924 | 01720320 | 01718825 | 01721384 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713820 | 01715814 | 01720346 | 01718733 | 01721398 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713818 | 01715925 | 01720263 | 01718771 | 01721364 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 41 of 50

Non-negotiable

| a | 70 | 7 | 1 | |
|-----|-------|----|-------|---|
| - M | 5 | 1- | | |
| 105 | 70 (| LП | | |
| 40 | NOT Y | | A A S | 9 |


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713817 | 01715981 | 01720269 | 01718801 | 01721389 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713834 | 01715920 | 01720358 | 01718811 | 01721397 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713809 | 01716007 | 01720303 | 01718816 | 01721388 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713819 | 01715972 | 01720305 | 01718827 | 01721418 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713198 | 01715958 | 01720316 | 01718838 | 01721355 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713726 | 01715976 | 01720344 | 01718777 | 01721425 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713784 | 01715977 | 01720227 | 01718769 | 01721444 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713751 | 01715968 | 01720330 | 01718845 | 01721450 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713750 | 01715942 | 01720290 | 01718751 | 01721399 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713723 | 01715986 | 01720283 | 01718819 | 01721467 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712902 | 01715980 | 01720302 | 01718844 | 01721449 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713772 | 01715956 | 01720294 | 01718855 | 01721401 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713771 | 01715987 | 01720273 | 01718804 | 01721245 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713782 | 01715966 | 01717829 | 01718887 | 01721411 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713730 | 01715970 | 01720241 | 01718654 | 01721409 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713703 | 01715999 | 01720363 | 01718441 | 01721325 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713012 | 01715963 | 01720334 | 01718645 | 01721405 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713005 | 01715967 | 01720367 | 01718445 | 01721414 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 42 of 50

Non-negotiable




| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713741 | 01715781 | 01720335 | 01718794 | 01721391 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713644 | 01715964 | 01720341 | 01718795 | 01721403 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713787 | 01715969 | 01720349 | 01718784 | 01721446 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713736 | 01715997 | 01720350 | 01718740 | 01721489 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713739 | 01715989 | 01720336 | 01718787 | 01721468 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713643 | 01715948 | 01720329 | 01718832 | 01721330 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01712857 | 01715954 | 01720343 | 01718793 | 01721494 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717172 | 01718068 | 01721934 | 01720714 | 01719332 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716952 | 01717916 | 01721884 | 01720702 | 01724479 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716961 | 01717974 | 01721961 | 01720841 | 01724431 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716963 | 01717972 | 01721856 | 01720815 | 01724462 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717000 | 01718048 | 01721978 | 01720848 | 01724400 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717030 | 01718031 | 01722011 | 01720836 | 01724483 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717010 | 01718084 | 01721885 | 01720734 | 01724433 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716986 | 01718057 | 01722010 | 01720849 | 01724522 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716999 | 01718061 | 01721912 | 01720858 | 01724415 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717003 | 01718051 | 01721982 | 01720840 | 01724377 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717048 | 01718025 | 01721854 | 01720857 | 01724383 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 43 of 50

Non-negotiable

| 0 | 30 | 30 | |
|---|----|-----|--|
| - | | - I | |
| 4 | | | |


| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716971 | 01718035 | 01721927 | 01720901 | 01724434 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716899 | 01718026 | 01721909 | 01720824 | 01724426 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717020 | 01718036 | 01721691 | 01720877 | 01724442 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717024 | 01718027 | 01721951 | 01720917 | 01724440 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717046 | 01717976 | 01721774 | 01720844 | 01724408 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717111 | 01717940 | 01721958 | 01720870 | 01724438 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717072 | 01718044 | 01721750 | 01720837 | 01724448 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716887 | 01717981 | 01721948 | 01720906 | 01724444 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717002 | 01718072 | 01721858 | 01720783 | 01724477 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716868 | 01718030 | 01721984 | 01720864 | 01724465 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716864 | 01718032 | 01722013 | 01720886 | 01724449 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717071 | 01718073 | 01722003 | 01720794 | 01724446 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717051 | 01718045 | 01722029 | 01720881 | 01724447 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717093 | 01718074 | 01722039 | 01720867 | 01724453 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717075 | 01718024 | 01722007 | 01720754 | 01724533 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717091 | 01718077 | 01721925 | 01720900 | 01724460 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01716866 | 01718011 | 01721897 | 01720869 | 01724463 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717139 | 01718085 | 01722031 | 01720896 | 01724467 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 44 of 50

Non-negotiable




| Mono Sol | ar Module | | LR5-72HTH-575M | |
|---------------|---------------|---------------|----------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717146 | 01718066 | 01722053 | 01720911 | 01724471 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717136 | 01717837 | 01722037 | 01720806 | 01724428 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717127 | 01718070 | 01722021 | 01720897 | 01719328 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717092 | 01717978 | 01722046 | 01720850 | 01719307 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717167 | 01718078 | 01721936 | 01720903 | 01724478 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717175 | 01718087 | 01721917 | 01720905 | 01724473 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01717157 | 01718019 | 01721864 | 01720895 | 01724454 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715236 | 01716120 | 01716650 | 01718927 | 01721417 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715197 | 01716063 | 01716672 | 01718928 | 01724475 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714478 | 01716058 | 01716673 | 01718892 | 01719343 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715237 | 01716057 | 01716721 | 01718895 | 01719361 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715233 | 01716076 | 01716670 | 01718687 | 01719337 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715223 | 01716075 | 01716776 | 01718826 | 01724472 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713524 | 01716071 | 01716668 | 01718731 | 01719336 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715181 | 01716069 | 01716679 | 01718629 | 01719338 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715203 | 01716059 | 01716681 | 01718702 | 01719364 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715218 | 01715940 | 01716645 | 01718885 | 01719339 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715215 | 01716073 | 01716534 | 01718835 | 01719342 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 45 of 50

Non-negotiable




| Mono Solar Module | | LR5-72HTH-575M | | |
|-------------------|---------------|----------------|---------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715222 | 01716068 | 01716647 | 01718627 | 01724425 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715254 | 01716066 | 01716606 | 01718904 | 01719325 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715252 | 01716072 | 01716644 | 01718901 | 01719316 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715255 | 01716070 | 01716628 | 01718641 | 01719327 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715249 | 01716043 | 01716528 | 01718900 | 01724491 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715221 | 01716067 | 01716611 | 01718852 | 01724524 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715243 | 01716013 | 01716646 | 01718902 | 01719308 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715226 | 01716053 | 01716725 | 01718742 | 01719333 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715229 | 01715909 | 01716519 | 01718911 | 01724403 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714033 | 01716055 | 01716614 | 01718874 | 01724401 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714031 | 01715990 | 01716652 | 01718926 | 01724399 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714032 | 01715372 | 01716641 | 01718644 | 01724490 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713964 | 01715381 | 01716592 | 01718878 | 01724546 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714042 | 01715821 | 01716656 | 01718755 | 01724395 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714041 | 01716035 | 01716635 | 01718873 | 01719331 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714053 | 01716032 | 01716643 | 01718847 | 01719330 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714039 | 01716026 | 01716633 | 01718883 | 01719329 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714040 | 01716031 | 01716613 | 01718725 | 01719315 |



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 46 of 50

Non-negotiable

| Mono Solar Module | | LR5-72HTH-575M | | |
|-------------------|---------------|----------------|---------------|---------------|
| MODULE ID | MODULE ID | MODULE ID | MODULE ID | MODULE ID |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714050 | 01716008 | 01716621 | 01718813 | 01724492 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714049 | 01716018 | 01716604 | 01718727 | 01724466 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714037 | 01716011 | 01716610 | 01718868 | 01724486 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01713980 | 01716040 | 01716609 | 01718860 | 01724544 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01714057 | 01716012 | 01716608 | 01718635 | 01724439 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715209 | 01716038 | 01716589 | 01718739 | 01724484 |
| LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 | LRP0041312307 |
| 01715183 | 01715975 | 01716661 | 01718889 | 01724437 |

12. Photos






The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 47 of 50

Non-negotiable







Visual check

Visual check





Module Lable

Size check





Size check


Size check



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at https://www.sgs.com/en/Terms-and-Conditions.aspx.. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 48 of 50

Non-negotiable








Size check

Size check





IV test

Safety testing





J-Box


Cable



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 49 of 50

Non-negotiable







J-Box- connector

J-Box- connector





Length of cord

Length of cord



IEC_61215_61730_2016 certificate

TUV LONGI Green Energy Technology Co., Ltd.

No. 388, Middle Hangtian Road, Chang'an District, Xl'a
Shaansi 710100, P.R. China e publication may be reproduced in whote or in part for non-commental purposes as they as the ECCE is echnomically as a second of the produced of the produced of the produced of the produced of the reproduced material due to its placement and context. This transfer of form is used by non-lifected members, the ICCEFERGE own and the produced of the produced of the ICCEFERGE own and the produced of the ICCEFERGE own and ICCEFFERGE own and ICCEFERGE own and ICCEFERGE own and ICCEFERGE own is report in not valid as a CB Test Report unless signed by an approved CB Testing Laboratory of appended to a CB Test Certificate issued by an NCB in accordance with ECCE 02. Invarid thickness:


IEC_61215_61730_2016 test report



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. IND



Page 50 of 50

Non-negotiable





THIS REPORT ONLY REFLECTED OUR ACTUAL FINDINGS. THE INSPECTION WAS DONE TO THE BEST OF OUR KNOWLEDGE AND ABILITY AND WITH DUE CARE. THE FINDINGS ARE VALID AS FOR TIME AND PLACE OF INSPECTION.

Young Yang Approved by: Reviewed by: Issued by: Min Tang

Title or Title or Title or Inspection Inspector Coordinator position: position: position: manager

Date: Aug.21, 2023 Date: Aug.22, 2023 Date: Aug.22, 2023

End of Report



The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of

The report would be invalid without authorized signature. The report shall not be reproduced except in full, without written approval of the Company.

This document is issued by the Company under its General Conditions of Service accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx, Attention is drawn to the limitation of ilability, indemnification and jurisdiction issues defined therein.

Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.