

INSPECTAI

Industrial Inspection Report

Inspection Details

Inspection	Lab Inspection
Location	Kota
Inspector	Raj
Inspection Date	2026-09-03
Status	completed
Risk Level	HIGH
Compliance Score	75%

Inspection Summary

The inspection was assessed with an overall risk level of **HIGH** and a compliance score of **75%**. A total of **5** finding(s) were identified.

Inspection Findings

1. Obstructed emergency exit

Severity	HIGH
Category	Safety
Status	OPEN
Page	1
Source	filename.pdf

Description: An emergency exit was partially obstructed by stored material

Recommendation: Clear the emergency exit immediately

2. Missing electrical warning labels

Severity	MEDIUM
Category	Electrical
Status	RESOLVED
Page	1
Source	filename.pdf

Description: Two electrical panels were missing updated warning labels

Recommendation: Replace the missing electrical warning labels

3. Missing eye protection

Severity	HIGH
Category	Safety
Status	IN PROGRESS
Page	1
Source	filename.pdf

Description: One worker was observed without the required eye protection in the machining area

Recommendation: Enforce the mandatory eye protection requirement

4. Loose machine guard

Severity	HIGH
Category	Machinery
Status	RESOLVED
Page	1
Source	filename.pdf

Description: A protective guard was loose and should be secured before continued heavy operation

Recommendation: Secure and inspect the machine guard

5. Excessive machine vibration

Severity	MEDIUM
Category	Equipment Condition
Status	OPEN
Page	1
Source	filename.pdf

Description: The main production machine was operational but showed excessive vibration near the drive assembly

Recommendation: Investigate and service the machine

Corrective Actions

Action	Assigned To	Priority	Due Date	Status
Emergency exits	Golu	HIGH	2026-10-21	OPEN