

INSPECTAI

Industrial Inspection Report

Inspection Details

Inspection	Safty Inspection
Location	Jaipur
Inspector	Kranti
Inspection Date	2026-09-07
Status	completed
Risk Level	MEDIUM
Compliance Score	80%

Inspection Summary

The inspection was assessed with an overall risk level of **MEDIUM** and a compliance score of **80%**. A total of **5** finding(s) were identified.

Inspection Findings

1. Excessive Machine Vibration

Severity	MEDIUM
Category	Operational
Status	OPEN
Page	2
Source	filename.pdf

Description: The main production machine was operational but showed excessive vibration near the drive assembly.

Recommendation: Investigate and service

2. Loose Machine Guard

Severity	MEDIUM
Category	Machinery
Status	OPEN
Page	3
Source	filename.pdf

Description: One protective guard was loose and should be secured before continued heavy operation.

Recommendation: Inspect and secure

3. Obstructed Emergency Exit

Severity	HIGH
Category	Safety
Status	OPEN
Page	5
Source	filename.pdf

Description: An emergency exit was partially obstructed by stored material.

Recommendation: Clear immediately

4. Missing Electrical Warning Labels

Severity	MEDIUM
Category	Electrical
Status	OPEN
Page	4
Source	filename.pdf

Description: Two electrical panels were missing updated warning labels.

Recommendation: Replace labels

5. Missing Eye Protection

Severity	HIGH
Category	Safety
Status	IN PROGRESS
Page	4
Source	filename.pdf

Description: One worker was observed without the required eye protection in the machining area.

Recommendation: Enforce PPE requirement

Corrective Actions

Action	Assigned To	Priority	Due Date	Status
Emergency exits	Golu	HIGH	2026-10-21	OPEN
corrective measures	Pankaj	HIGH	2026-09-10	RESOLVED