

INSPECTAI

Industrial Inspection Report

Inspection Details

Inspection	house safety
Location	Kota
Inspector	Abhishek
Inspection Date	2026-09-14
Status	completed
Risk Level	HIGH
Compliance Score	80%

Inspection Summary

The inspection was assessed with an overall risk level of **HIGH** and a compliance score of **80%**. A total of **4** finding(s) were identified.

Inspection Findings

1. Obstructed fire-equipment access

Severity	CRITICAL
Category	Fire
Status	OPEN
Page	1
Source	warehouse_inspection.pdf

Description: A fire-extinguisher access zone was partially obstructed by packaging material.

Recommendation: Clear immediately

2. Pallet near aisle boundary

Severity	MEDIUM
Category	Structural
Status	OPEN
Page	1
Source	warehouse_inspection.pdf

Description: One pallet was positioned close to an aisle boundary and should be relocated to maintain clear access.

Recommendation: Relocate pallet

3. Damaged warning sign

Severity	LOW
Category	Safety
Status	OPEN
Page	1
Source	warehouse_inspection.pdf

Description: One storage-area warning sign was damaged.

Recommendation: Replace sign

4. Packaging waste

Severity	LOW
Category	Environmental
Status	IN PROGRESS
Page	1
Source	warehouse_inspection.pdf

Description: Packaging waste was present near the loading area and should be removed at the end of the shift.

Recommendation: Remove and clean

Corrective Actions

Action	Assigned To	Priority	Due Date	Status
Clear Pipe	Abhishek	HIGH	2026-09-17	RESOLVED