

INSPECTAI

Industrial Inspection Report

Inspection Details

Inspection	gfidg
Location	Delhi
Inspector	igt8s
Inspection Date	2026-09-08
Status	completed
Risk Level	HIGH
Compliance Score	90%

Inspection Summary

The inspection was assessed with an overall risk level of **HIGH** and a compliance score of **90%**. A total of **3** finding(s) were identified.

Inspection Findings

1. Partially blocked exit

Severity	HIGH
Category	Safety
Status	OPEN
Page	1
Source	Fire Safety Inspection.pdf

Description: A storage box was found partially obstructing an emergency exit route. The affected exit should be cleared immediately and the area should be monitored to prevent recurring obstruction.

Recommendation: Clear immediately

2. Outdated extinguisher tag

Severity	MEDIUM
Category	Safety
Status	OPEN
Page	1
Source	Fire Safety Inspection.pdf

Description: One extinguisher inspection tag requires updating.

Recommendation: Update inspection tag

3. Faded fire sign

Severity	LOW
Category	Safety
Status	OPEN
Page	1
Source	Fire Safety Inspection.pdf

Description: One fire-safety sign near the warehouse entrance was faded.

Recommendation: Replace signage

Corrective Actions

No corrective actions have been created.