





Command: [0.0, 0.5, 0.5, 0.0, 0.0, 0.0]





- |R4\_Pitch Error|

--- R4\_Pitch Mean: 0.0000 rad

## Statistical Analysis of Arm Joint Errors

Joint	Mean Error (rad)	Standard Deviation (rad)
R0_Yaw	0.0173	0.0150
R1_Pitch	0.2813	0.2106
R2_Pitch	0.2475	0.2001
R3_Yaw	0.1135	0.1028
R4_Pitch	0.0000	0.0002