




Command: [0.0, 0.5, 0.5, 0.0, 0.0, 0.0]



|R0\_Yaw Error|
R0\_Yaw Mean: 0.0025 rad
|R1\_Pitch Error|
R1\_Pitch Mean: 0.0195 rad
|R2\_Pitch Error|
R2\_Pitch Mean: 0.0201 rad

|R3\_Yaw Error|R3\_Yaw Mean: 0.0179 rad|R4\_Pitch Error|

--- R4\_Pitch Mean: 0.0000 rad

## Statistical Analysis of Arm Joint Errors

Joint	Mean Error (rad)	Standard Deviation (rad)
R0_Yaw	0.0025	0.0032
R1_Pitch	0.0195	0.0129
R2_Pitch	0.0201	0.0121
R3_Yaw	0.0179	0.0138
R4_Pitch	0.0000	0.0002