





Command: [0.0, 0.5, 0.5, 0.0, 0.0, 0.0]





--- R4_Pitch Mean: 0.0000 rad

- |R4_Pitch Error|

Statistical Analysis of Arm Joint Errors

Joint	Mean Error (rad)	Standard Deviation (rad)
R0_Yaw	0.0010	0.0010
R1_Pitch	0.0055	0.0033
R2_Pitch	0.0066	0.0031
R3_Yaw	0.0327	0.0601
R4_Pitch	0.0000	0.0001