


```
.options vntol=1m abstol=1u
.param tdv=1 tdt=1 fn1=50
.param omega_n={2*pi*fn1}
```

```
.tran 0 1000ms 0 0.1ms
```

U1Nenn=115k FREQU=50 Texp=5m TD=0

psir=1 psis=-0.5 psit=-0.5 (default)



**Psi is only dependant of
U and N1(windings)**

Psi = Phi*N1
Psi=U(phase_peak)/omega

N1=1000

U=115000*sqrt(2)/sqrt(3)
=93883V (Peakvalue)

PhiN=U/omega/N1=
93883/314.159/1000
=0.2988 (Peakvalue)

