





Most used devices/symbols

	V_3phase.asy sources.lib	Three phase voltage source with optional exponential or linear swingin		sg.asy sgen.lib	Synchronous generator round pole: Schenkelpolfaktor ~ 1 Kc $\sim 0.4-0.65$ salient pole: Schenkelpolfaktor ~ 0.5 Kc $\sim 0.8-1$
	Line_special.asy Line.lib	Overhead line and cable uncoupled, transposed		trafo_Yd.asy trafo_Yd.lib	Transformers with different vector groups Yd,Dy,Yy,Yz
	Line2.asy Line2.lib	Overhead line and cable coupled, transposed, distributed or lumped		Pet.asy comp.lib	Petersen coil for earth fault compensation
	Line2_coupled Line_coupled.lib	Coupled Overhead line lumped, untransposed		trafo_gnd.asy trafo_gnd.lib	Artificial external starpoint To use for Yd Dy transformers
	Line_cable_shield.asy Line_coupled.lib	Coupled cable with shield lumped, untransposed		Switcher.asy Switcher.lib	Switcher initially open
	Load_d.asy Load.lib	Delta Load R,L,C		Switcher_off.asy Switcher.lib	Switcher initially closed
	Load_y.asy Load.lib	Wye Load R,L,C		Fault_earth.asy Switcher.lib	Earth fault switcher
	impedance.asy impedance_sk.asy impedance.lib	Impedance with R,L Impedance with sk (short circuit capacity)		Fault_earth_1phase.asy Switcher.lib	Earth fault switcher one phase
	Lbatt.asy comp.lib	Shunt reactance for voltage regulation		isolator.asy isolator.lib	Isolator
	Cbatt.asy comp.lib	Capacitor bank for voltage regulation		bus_veff.asy measure.lib	Bus measurement VRMS L-L phase A,B,C
	v/a/p/q/s-meter.asy measure.lib	RMS-Metering devices		bus_veff_phase.asy measure.lib	Bus measurement VRMS L-L,L-N,Phaseangle Phase A