

Synchronous 400V generator

Generator has variable magnetic field voltage (0 to 96V)

Generator has fixed speed at 1500

Generator is not loaded

Schenkelpolfaktor=1 (cylindrical pole machine)

$a=0.6-0.9$ $m=7$ (nonlinear magnetics - with saturation)

