
Petersen with fault loaded vs unloaded (AC-analysis)

.options vntol=1m abstol=1u
.ac lin 1000 48 52

.param tdv=1 tdt=1 fn1=50
.param omega_n={2*pi*fn1}
.param ce=5012n ce1=10n
.param last=20e-6 last1=40e6

V_3Phase_AC
U1Nenn={110k}

Load 40 MW/8 MVAr




VN={110k} IN={328} fN=50

V_3Phase_AC
U1Nenn={110k}

The starpoint voltage decrease with the load especially at inductive load

Load 0MW



VN={110k} IN={328} fN=50