Function name	HLCD_vInit			
Arguments	Input			
	Output		none	
Return		none		
Description			Initialize LCD prephiral	
	•			
Function name			HLCD_vSendCommand	
Angumanta	Input	A_u8Cmd	Command sent to LCD	
Arguments	Output	none		
Return		-	none	
Description			Send command to lcd	
	•			
Function name			HLCD_vSendData	
A 400040 0440	Input	A_u8Data	Data sent to LCD	
Arguments	Output		none	
Return			none	
Description			Send data to lcd	
Function name			HLCD_vClear	
A	Input		none	
Arguments	Output	none		
Return		none		
Description		Clear LCD		
Function name		HLCD_vDispString		
Arguments	Input	* A_c8Char	Pointer to string to be displayed on lcd	
Arguments	Output		none	
Return		none		
Description		Display sent string on LCD		
Function name			HLCD_vDispNumber	
Arguments	Input	A_s32Num	Number to be displayed on lcd	
Arguments	Output		none	
Return			none	
Description	Display sent number on LCD			
Function name			HLCD_vSaveCustomChar	
Arguments	Input	A_u8Address	Address of the custum char to be saved	
	шриі	* A_u8CustomChar	Pointer to the custom character	
	Output	none		
Return		none		
Description			Save customed character	

Function name	HLCD_vSaveDispChar			
	т.	A_u8Address	Address of the custum char to be dissp;aye	
Arguments	Input	* A_u8CustomChar	Pointer to the custom character	
J	Output		none	
Return		•	none	
Description	Display the customed character			
	•			
Function name			HLCD_vGoTo	
	Input	A_u8Row	The lcd row number	
Arguments		A_u8Col	The lcd column number	
	Output		none	
Return			none	
Description		///////////////////////////////////////	//////////*//*/	
Function name			HLCD_vSetShiftLeftOn	
Arguments	Input		none	
ruguments	Output	none		
Return	none		none	
Description	This function is responsible for setting shift right on			
Function name	HLCD_vSetDispOFF			
Arguments	Input	none		
ŭ	Output	none		
Return	none			
Description			Turn off the display	
Function name	HLCD_vDispCursorWithBlinking			
Arguments	Input	none		
ŭ	Output	none		
Return	none			
Description				
Function name	HLCD_vSetCursorBlinkingOFF			
Arguments	Input			
ŭ	Output	none		
Return	none			
Description			///////////////////////////////////////	
Function name			HLCD_vDispShiftLeftString	
Arguments	Input	* A_c8Char	/////////	
	Output		none	

Return	none		
Description			
Function name	HLCD_vClearChar		
	Input	A_u8Row	//////////
Arguments		A_u8Col	///////////////////////////////////////
	Output	none	
Return	none		
Description			

 1	
-	
İ	
1	
•	
 1	

d
-

