



Frank Mohn Services AS


No.2-1990

Service Bulletin

MAKE YOU UP TO DATE WITH THE LATEST NEWS FROM FRANK MOHN SERVICES AS

- NEW DESIGN - HYDRAULIC PISTON PUMPS

Spare parts recommendation.



FIXED DISPLACEMENT
UNIT



FRANK MOHN
SERVICES AS
Hardangerveien 150
PO. Box 98
N-5051 Nesttun
Norway
Phone: 47 5 99 92 00
Telex: 42 927 framo n
Telefax: 47 5 99 93 82

FRANK MOHN
NEDERLAND BV
Edisonweg 14
PO. Box 305
NL-3200 AH Spijkenisse
The Netherlands
Phone: 31 1880 19 311
Telex: 29 643 framo nl
Telefax: 31 1880 11 193

FRANK MOHN
HOUSTON INC
1802 West D-Street
PO. Box 1586, La Porte
Texas 77571
USA
Phone: 1 713 471 7920
Telex: 68 68 120 framo lapl
Telefax: 1 713 470 1258

FRANK MOHN
SINGAPORE PTE LTD
16 Tuas Crescent
Singapore 2263
Republic of Singapore
Phone: 65 861 4455
Telex: 35 446 framo rs
Telefax: 65 861 5910

DEAR FRAMO CUSTOMER!


Please be informed that the old type "Baureihe 2" hydraulic piston pumps are no longer being manufactured. Consequently complete units are no longer available. Spare rotary groups will, however, be available for a limited time.

Generally, however, spare parts will have long delivery time with a limited availability and unfortunately the prices will increase due to smaller series.

Experience shows that the lifetime of modern tankers is extended far beyond the original expectancy. This lifetime extension makes it necessary to replace obsolete products infor today's design.


Fortunately, in this case, the manufacturer has made the new design such that only minor modifications are necessary.

Size: 87 - 107 - 125 - 160 - 182 - 225



Size: 200 - 250 - 379 (355)


Today's design: "Baureihe 6"



NB: Size 379 is obsolete and has to be replaced by 355 or a combination of 355 and 500 may be necessary to obtain the same oilflow.

Size 468 (500) - 740 (710) - 915 (1000)

For these bigger sizes "Baureihe 5" is still the current type



Additional advantages:

- Bearing flushing system is required to obtain optimal lifetime
- Calculated lifetime will increase 4 - 6 times compared to "Baureihe 2"

FRAMØ Services can offer you:

- Inspection of the installation to evaluate the necessary modifications.
- Design and specify required parts
- Supply necessary pumps and other parts
- Undertake the complete installation
- Recommissioning the powerside to ensure a long and troublefree operation of the system.

For further information please do not hesitate to contact us !

Very truly yours
pr. FRAMØ SERVICES A/S

Svein Andersen