

**TO:** Dick Coulombe

HID Global

611 Center Ridge Drive

Austin, TX 78753

**FROM:** Matt Arnold on behalf of the FICAM Testing Program

**DATE:** 10/13/2020

**RE:** Updated Approval of Products/Services for Listing on the GSA APL

Office of Management and Budget (OMB) issued M-19-17 that requires Federal Agencies to procure only qualified products and services listed on the GSA Approved Products List (APL) when implementing HSPD-12 into their environment. Procurement of approved products and services facilitates the government-wide objective of a federated and interoperable ICAM segment architecture, and ensures compliance, consistency and alignment of commercially-available products and services with the requirements and functional needs of government ICAM implementer.

Accordingly, the FIPS 201 Evaluation Program (Program) is very pleased to inform you that the following product/service has passed testing against all applicable Testing Requirements. Please see the attached document that summarizes the specific parameters of the approval (e.g., product/service profile, what your product/service was tested with). Your product/service will now be listed on the APL as shown below. If there are any errors in the listing information, please notify me within five (5) business days of receiving this letter.

# **Approval Authorization Letter**

## 1 Category-Validation System

## 1.1 APL Certification Number

- (APL# **10062**)
  - o pivCLASS Registration Engine for Genetec Synergis
  - o pivCLASS Certificate Manager
  - o pivCLASS Reader Services
  - o pivCLASS Authentication Module
  - o pivCLASS IDPublisher<sup>1</sup>

## 1.2 Product/Service Information

Organization Name:	HID Global
Name of Product or Service:	pivCLASS Registration Engine for Genetec Synergis
Part Number:	PVCP-D/S-27-00
Hardware Version:	
Software Version:	5.13.0.0
Firmware Version:	

Organization Name: HID Global	
Name of Product or Service:	pivCLASS Certificate Manager
Part Number:	PVC-CM
Hardware Version:	
Software Version:	5.13.0.0
Firmware Version:	

Organization Name:	HID Global
Name of Product or Service:	pivCLASS Reader Services
Part Number:	PVC-FXRDR
Hardware Version:	
Software Version:	5.13.0.0
Firmware Version:	

Organization Name:	HID Global
Name of Product or Service:	pivCLASS Authentication Module
Part Number:	91000ABNNN
Hardware Version:	
Software Version:	
Firmware Version:	5.13.0.0

Organization Name:	HID
Name of Product or Service:	pivCLASS IDPublisher <sup>1</sup>

<sup>&</sup>lt;sup>1</sup> Meets one or more optional test cases in FRTC, but not required for minimum FICAM compliance.

Part Number:	PVC-IDPUBUNL
Hardware Version:	
Software Version:	5.13.0.0
Firmware Version:	

## 1.3 Document History

Status	Date	Comments
Approved	7/14/2014	Final Approval Date for APL# 10028: HID pivCLASS Registration Engine for Lenel OnGuard 6 Software Version 1.2.270.0
Update	7/7/2015	Final Approval Date for Upgrade of HID pivCLASS Software Version to 1.2.285.0 and addition of HID pivCLASS RKCLB40 Reader
Update	8/18/2017	Final Approval Date Upgrade of Software Version of Genetec Synergis 5.6.781 and HID pivCLASS Validation System Software Version 1.3.4.0
Update	2/20/2019	Final approval date - Upgraded to pivCLASS 5.7.1 with Synergis 5.7.946. Added pivCLASS Embedded Authentication, F/W Rev. 5.7.18 to Mercury LP-4502.
Update	10/13/2020	Product update for Synergis 5.9.1 and HID pivCLASS 5.13.0.0. Distinction made of embedded configuration and Authentication Module configuration.

### 1.4 Restrictions:

This product has been tested and approved as a component of a fully compliant FICAM Solution. The end to end solution components used to test the FICAM compliance of the approved solution are listed below.

- PACS Infrastructure (APL #10061)
  - Common Components
    - Genetec Security Center Synergis Physical Access Control System
    - Synergis Cloudlink Master Controller Kit
  - o Embedded Authentication Configuration
    - Mercury LP-4502 Intelligent Controller
    - Mercury MR52-S3 Two-Reader Interface
    - Mercury MS50-S3 Single Reader Interface
  - o pivCLASS Authentication Module Configuration
    - Mercury LP-1502 Two-Door Controller
    - Mercury MS52-S3 Two-Reader Interface
    - Mercury MS50-S3 Single Reader Interface
    - HID pivClass Authentication Module

#### • PIV Reader

#### HID Readers

- o pivCLASS RPKCL40 Contact/Contactless Reader with PIN (APL# 10008)
- o pivCLASS RKCL40 Contact/Contactless Reader (APL# **10007**)
- o pivCLASS RPK40 Contact/Contactless Reader (APL# **10005**)
- o pivCLASS RK40 Contactless Reader (APL# 10004)
- o pivCLASS RP40 Contactless Reader (APL# **10003**)
- o pivCLASS R40 Contactless Reader (APL# **10006**)
- pivCLASS RPKCLB40 Contact/Contactless Reader with PIN & BIO (APL# 10026)
- pivCLASS RKCLB40 Contact/Contactless Reader with PIN & BIO (APL# 10052)
- o pivCLASS R10 Contactless Reader (APL# 10085)

#### Veridt Reader

- Veridt Stealth Lite Contactless Reader (APL# 10096)
- o Veridt Stealth Contactless Keypad Reader (APL# 10095)
- Veridt Bio Dual Contact/Contactless Keypad Reader (APL#10094)
- Veridt Stealth Dual Contact/Contactless Keypad Reader (APL# 10093)
- Veridt Bio Dual Contact/Contactless Keypad Reader (APL# 10092)

Approval of the above product/service indicates your cooperation with the Program and successful testing against a rigorous, comprehensive set of functional requirements derived from government-wide specifications. Testing included positive and negative test cases, and threat vectors.

Given the strategic government-wide importance of the APL, the scope and extent of testing performed on your product/service, and the rigor of that testing, the Program would like to acknowledge the noteworthiness of the approval and listing. Your product/service will now be available to all Federal Agencies for procurement.

Please note that continued listing on the APL requires ongoing conformance to all applicable requirements, including requirements added or amended over time. A listed product/service can become non-conformant for various reasons including but not limited to:

- Failure to pass testing against new and revised requirements before the effective date of the new/revised requirements.
- Problems discovered in your listed product/service (or class of product/service) are not addressed within time frames specified by the Program.

Refer to applicable Agreements and Program documents for specific details regarding ongoing compliance including severity levels and remediation time frames. Listed products and services that fall out of conformance will be removed from the APL and added to the Removed Products List (RPL).

If you have any questions, please feel free to contact me.

Matthew Arnold GSA OGP (703) 254-6750 Matthew.Arnold@gsa.gov