

**TO:** François Brouillet

Genetec

2280 Alfred-Nobel Boulevard

Suite 400 Saint-Laurent

Quebec, Canada H4S 2A4

**FROM:** Matt Arnold on behalf of the FICAM Testing Program

**DATE:** 2/4/2021

**RE:** Updated Approval of Products/Services for Listing on the GSA APL

Office of Management and Budget (OMB) issued M-19-17 that requires Federal Agencies to procure only qualified products and services listed on the GSA Approved Products List (APL) when implementing HSPD-12 into their environment. Procurement of approved products and services facilitates the government-wide objective of a federated and interoperable ICAM segment architecture, and ensures compliance, consistency and alignment of commercially-available products and services with the requirements and functional needs of government ICAM implementer.

Accordingly, the FIPS 201 Evaluation Program (Program) is very pleased to inform you that the following product/service has passed testing against all applicable Testing Requirements. Please see the attached document that summarizes the specific parameters of the approval (e.g., product/service profile, what your product/service was tested with). Your product/service will now be listed on the APL as shown below. If there are any errors in the listing information, please notify me within five (5) business days of receiving this letter.

# Approval Authorization Letter

## 1 Category-PACS Infrastructure (APL #10061)

### 1.1 APL Certification Number

- (APL #10061)
  - Common Components
    - Genetec Security Center Synergis Physical Access Control System
    - Synergis Cloudlink Master Controller Kit
  - o Embedded Authentication Configuration
    - Mercury LP-4502 Intelligent Controller
    - Mercury MR52-S3 Two-Reader Interface
    - Mercury MS50-S3 Single Reader Interface
  - o pivCLASS Authentication Module Configuration
    - Mercury LP-1502 Two-Door Controller
    - Mercury MS52-S3 Two-Reader Interface
    - Mercury MS50-S3 Single Reader Interface
    - HID pivClass Authentication Module

### 1.2 Product/Service Information

Organization Name:	Genetec
Name of Product or Service:	Security Center – Synergis
Part Number:	GS-SYS-x**
Hardware Version:	N/A
Software Version:	5.9.1
Firmware Version:	N/A

<sup>\*\*</sup> Note: Part numbers ending in "x" that are specifically defined in the table below are approved under APL #10061. Any value for "x" that is not defined below has not been tested and approved hereunder.

"x"	Description
S – Standard	Includes up to 64 readers and a single Access Manager Role
P – Pro	Includes up to 256 readers and up to two Access Manager Roles
E - Enterprise	Includes unrestricted number of readers and Access Manager Roles

Organization Name:	Genetec
Name of Product or Service:	Synergis Master Controller Kit
Part Number:	SY-CLOUDLINK
Hardware Version:	
Software Version:	11.0
Firmware Version:	1

Organization Name:	Mercury
Name of Product or Service:	LP-1502 Two-Door Controller

Part Number:	SY-LP1501
Hardware Version:	N/A
Software Version:	N/A
Firmware Version:	1.29.0

Organization Name:	Mercury
Name of Product or Service:	LP-4502 Intelligent Controller with HID pivCLASS
	Embedded Authentication
Part Number:	SY-LP4502
Hardware Version:	N/A
Software Version:	N/A
Firmware Version:	1.29.0

Organization Name:	Mercury
Name of Product or Service:	MR52 Two-Reader Interface Module
Part Number:	SY-MR52-S3
Hardware Version:	Series 3
Software Version:	N/A
Firmware Version:	3.21.7

Organization Name:	Mercury
Name of Product or Service:	MR50 Single Reader Interface Module
Part Number:	SY-MR50-S3
Hardware Version:	Series 3
Software Version:	N/A
Firmware Version:	3.21.7

# 1.3 Document History

Status	Date	Comments
Approved	7/17/2015	Final Approval Date for APL# 10061
Update	8/18/2017	Updated Approval Date for Synergis 5.6.781 with HID pivCLASS 1.3.4.0 Validation System and HID pivCLASS PIV Readers
Update	2/20/2019	Updated Approval Date for Synergies 5.7.946 with HID pivCLASS 5.7.1 validation system and HID pivCLASS PIV Readers. Added HID pivCLASS Embedded Authentication to LP-4502. Removed HID VertX V100 controller.
Update	10/13/2020	Product update for Synergis 5.9.1 and HID pivCLASS 5.13.0.0. Distinction made of embedded configuration and Authentication Module configuration.
Correction	2/4/2021	Correction of Cloud Link software version.

### 1.4 Restrictions:

This product has been tested and approved as a component of a fully compliant FICAM Solution. The end to end solution components used to test the FICAM compliance of the approved solution are listed below.

- Validation System (APL# 10062)
  - o pivCLASS Registration Engine for Genetec Security Center Synergis Release
  - o pivCLASS Certificate Manager Release
  - pivCLASS Reader Services Release
  - o pivCLASS IDPublisher Release
  - o pivCLASS Authentication Module

### • PIV Reader

### HID Readers

- o pivCLASS RPKCL40 Contact/Contactless Reader with PIN (APL# 10008)
- o pivCLASS RKCL40 Contact/Contactless Reader (APL# 10007)
- o pivCLASS RPK40 Contact/Contactless Reader (APL# **10005**)
- o pivCLASS RK40 Contactless Reader (APL# 10004)
- o pivCLASS RP40 Contactless Reader (APL# **10003**)
- o pivCLASS R40 Contactless Reader (APL# **10006**)
- pivCLASS RPKCLB40 Contact/Contactless Reader with PIN & BIO (APL# 10026)
- pivCLASS RKCLB40 Contact/Contactless Reader with PIN & BIO (APL# 10052)
- o pivCLASS R10 Contactless Reader (APL# **10085**)

#### Veridt Reader

- Veridt Stealth Lite Contactless Reader (APL# 10096)
- o Veridt Stealth Contactless Keypad Reader (APL# 10095)
- o Veridt Bio Dual Contact/Contactless Keypad Reader (APL#10094)
- Veridt Stealth Dual Contact/Contactless Keypad Reader (APL# 10093)
- Veridt Bio Dual Contact/Contactless Keypad Reader (APL# 10092)

Approval of the above product/service indicates your cooperation with the Program and successful testing against a rigorous, comprehensive set of functional requirements derived from government-wide specifications. Testing included positive and negative test cases, and threat vectors.

Given the strategic government-wide importance of the APL, the scope and extent of testing performed on your product/service, and the rigor of that testing, the Program would like to acknowledge the noteworthiness of the approval and listing. Your product/service will now be available to all Federal Agencies for procurement.

Please note that continued listing on the APL requires ongoing conformance to all applicable requirements, including requirements added or amended over time. A listed product/service can become non-conformant for various reasons including but not limited to:

- Failure to pass testing against new and revised requirements before the effective date of the new/revised requirements.
- Problems discovered in your listed product/service (or class of product/service) are not addressed within time frames specified by the Program.

Refer to applicable Agreements and Program documents for specific details regarding ongoing compliance including severity levels and remediation time frames. Listed products and services that fall out of conformance will be removed from the APL and added to the Removed Products List (RPL).

If you have any questions, please feel free to contact me.

Matthew Arnold GSA OGP (703) 254-6750 Matthew.Arnold@gsa.gov