







Solder jumper JA1 is used when Unit-A is not loaded, solder jumper JB1 is used when Unit-B is not loaded, solder jumper JC1 is used when Unit-C is not loaded, and solder jumper JD1 is used when Unit-D is not loaded. Unit-A is loaded first, then Unit-B, then Unit-C, and then Unit-D.

(can be printed at 63% on 2 sheets (poster))

Copyright 2026 AESilky & SmM
SilkyDESIGN / CMOS1
Sheet: /
File: ZID_MAIN.kicad_sch

Title: Z80 In-Circuit Debugger (ZID)

Date: 2026-06-25
KiCad E.D.A. 9.0.9

Rev: PR-1.0
Id: 1/1