
Sectors and rotor positions of a 3 phase machine



Sectors and rotor positions of a 5 phase machine

