
## Sectors (rotor positions) and phase orientation of a 2 phase machine



Sectors (rotor positions) and phase orientation of an asynchronous 4 phase machine

