
Sectors (rotor positions) and phase orientation of a 3 phase machine



Sectors (rotor positions) and phase orientation of a 5 phase machine

