# Lake George Geary's Gap - Site Brief

This brief is for Duty Pilots (generally Safety Officers) to provide to all pilots. It should provide a basis for discussion of safe operations on the hill.

#### **Site Description and General Conditions:**

Geary's Gap is available for limited use, however the following needs to be understood at this time:

- we have very agitated landowners adjoining the site who do not respond well to any abusive or aggressive behaviour; and
- as a club, if we do not work on interactions with the landowners being a
  positive experience for both parties, the site will eventually become nonuseable due to the potential of legal action taking place.
- Lake George is an inland soaring ridge that faces towards the east.
- The launch is Crown land and the landing is privately owned.
- A key to the LZ gates can be provided by the club

#### Please don't contact PROPERTY OWNERS for access

Contact the club committee for any enquiries.

- Launch: S35° 05'46" E149° 22'29": 2400' (730m) AMSL
- LZ: S35°05'48" E149°22'37"
- Controlled airspace starts at 4500' AMSL; see VTC for other regional airspace
- Just over the back of the ridge airspace drops to 3500'

## Site Rating: [Describe as Guidelines]

- Wind Direction: NE to SE
- Site rating is dependent on conditions. Lake George conditions can be anywhere from benign to very dangerous. Some guidelines:
  - Novice PG Wind Gusting less than 24 kph
  - Novice HG Wind Gusting less than 35 kph
  - Intermediate PG Wind Gusting 22kph to 30kph
  - Intermediate HG Wind Gusting 39kph to 46kph
  - Advanced PG and HG To make own appraisal.
- Other factors will contribute to the assessment of safe launch conditions:
  - Is the wind strength trending up?
  - What is your airspeed on your wing?
  - Is it morning or afternoon?
  - What are the observations at other regional sites (i.e. Braidwood & Nerriga)?
  - How many other pilots are in the air?
  - Is the sea breeze coming?
  - How thermic is it?

## Weather Hazards: [Describe weather information sources]

- Has the sea breeze arrived or still coming in?
- Strong thermic conditions low to the ground during the middle of the day.
- If it is strong enough to stay up, it is strong on launch.

# Launch Hazards: [Describe launch areas]

- Barbed wire fence to the right of launch
- Turbulence from trees in strong winds.
- Venturi effect on launch requires good launch skills.
  Proximity to the highway
- House next to launch with horses

#### Landing Hazards: [Describe landing areas]

- Large open paddock with black berries close to road and fences
- Turbulence in thermic conditions on lake bed
- Strong rotor behind launch at Geary's in strong winds
- Safe top landing window for PG is very small. If it is strong enough to top land, it is
- often too strong to safely collapse your wing, especially if thermic or gusty
  Rotor may be experienced by trees out front at Geary's
- Lake George is home to one of the largest populations of Taipan snakes. These
  snakes are usually a shade of brown, are highly aggressive with rectangular shaped
  heads and their venom is highly venomous. If bitten, seek medical assistance as a
  matter of urgency. A decent bite, without medical assistance can be fatal within 45

#### In Flight Hazards: [Describe typical flight areas]

- A strengthening sea breeze
- Powerlines near the Weereewa lookout carpark.
- Increase distance from the ridge as the wind gets stronger is recommended.
- There have been reports of eagles both north and south of launch, causing damage to both hang gliders and paragliders.

### Site Closure Procedures:

minutes.

- A Duty Pilot might close the site due to unsafe conditions, or if there is an accident:
  - All pilots in the air must proceed to land immediately if the site is closed.
  - A cross symbol on launch or landing indicates the site is closed.
  - A pilot in the air sitting out of the harness indicating with running legs is another indication the site is closed.

## **Emergency Procedures:**

- In the event of an accident involving injury.
  - Call 000. Describe to the operator that the LZ location is at the intersection of Federal highway with the Barton highway and Hadlow Drive.
  - The site must be closed in the event of any injury that involves ambulance attendance (air or ground) from the moment the ambulance is called.
  - Report the incident by phone to an ACTHPA SSO to initiate the reporting mechanism.

### **Site Rules:**

- All pilots must be HGFA members.
- Drive on roads only no driving on grassed areas including paddocks.
- Parking only in carparks at launch or landing. No Dogs.

# **Site Recommendations:**

Pilots should monitor the HGFA UHF frequency (472.125Mhz) while in flight for notifications.

Site brief current: 17 September 2015