

Job Details

Report ID: **TEK247-DR-2026-0517**
Date: **21 June 2026**
Technician: **A. Jamiu (Lead Technician)**
Repair Ref: **Repair #5 - Software upgrade**

Device

Model: **Apple MacBook Pro 14-inch (M5 Max)**
Model No.: **A3427**
Serial: **C02XL0AJ3427 (hash anchored on-chain)**
Customer: **Jamiu Alade (ajtech255@gmail.com)**

Diagnostics Performed

[OK] Boot & power-on self test (POST) - passed
[OK] Storage SMART health - 100%, 0 reallocated sectors
[OK] Battery: 84 cycles, 98% of design capacity
[OK] Thermal/fan stress test (20 min) - max 78C, stable
[OK] Display, keyboard, trackpad, ports, Wi-Fi/BT - all OK
[OK] macOS integrity & malware scan - clean

Work Performed

[OK] Upgraded macOS to latest release; firmware/SMC updated
[OK] Migrated user data; re-validated licensed software
[OK] Cleaned cooling assembly, reapplied thermal paste
[OK] Full post-service QA and 24h burn-in

Outcome

Device passed all post-repair checks and is operating to specification. No hardware faults detected. Recommended next service in 12 months. This report is stored on Walrus and its SHA-256 hash is anchored to the device's on-chain Device Passport on Sui (testnet), making the repair history tamper-evident and verifiable on resale.

TEK247 - Trustless repairs & verifiable devices on Sui | <https://tek247.vercel.app> | Demo artifact for the Sui Overflow 2026 submission.