

FIRE HAZARD SEVERITY ZONE NOTICE

Transaction 48291 · v1 · Page 1 of 2

LOCATION ENTRY F-1

Subject 123 Main Street, Harborfield; APN 084-221-019; construction year 1988. Fictional screen DEMO-HF-FIRE-0824 reports no triggered additional fire-zone notice for this scenario. No real state or local map panel or inspection certificate is claimed. This entry is paired with NHD-48291-0824 rather than represented as an official agency determination.

PROPERTY OBSERVATIONS F-2

Visible rear planter abuts landscape edging; detached storage and tree canopies were not measured for defensible-space compliance. Seller has not supplied a current fire-district clearance or a home-hardening retrofit certificate. Roof-covering age is not established by this screen. No inspection pass, violation, or compliance deadline is fabricated. A local agency determination, if obtained, must identify the parcel, inspection date, and corrections required.

SELLER'S CONTINUATION — PRIOR WORK

During the first winter after purchase, wind-driven rain reached the interior sill of the rear bedroom window. A glazing contractor renewed the exterior seal in April 2021. Seller observed no recurrence during subsequent ordinary rain but did not open the wall cavity or obtain a mold assessment. In June 2023 a plumbing contractor replaced the kitchen faucet and flexible supply connectors; no relocation of a drain or supply line was included. The service invoices are identified in the repair index as R-04 and R-09. The seller does not possess drawings for the original construction and cannot identify concealed piping materials throughout the residence.

BUYER NOTICE F-3

Fire exposure can exist outside a mapped severity zone. Insurability and premium are determined separately by the insurer. If a later location review changes the applicability result, obtain the appropriate notices and any required local inspection through the responsible professionals. Receipt of this screen neither certifies defensible space nor excuses maintenance. The disclosure recipient should retain the later map or inspection version when a corrected result is issued.

KNOWLEDGE LIMITS AND RECORDS DELIVERED

Responses concern the seller's actual recollection during occupancy and are not a representation that an unobserved condition cannot exist. A response of 'not known' is different from a negative test result. Roof surfaces, foundation cavities, underground lines, and areas behind stored belongings have not been opened for purposes of these responses. Service papers delivered with the packet are identified by date rather than

FIRE HAZARD SEVERITY ZONE NOTICE

Transaction 48291 · v1 · Page 2 of 2

KNOWLEDGE LIMITS AND RECORDS DELIVERED — CONTINUED

adopted as the seller's independent expert opinion. Buyer may ask follow-up questions through the representatives and may employ qualified specialists within the investigation arrangements. Later knowledge of a material change shall be conveyed in a dated supplement identifying the earlier response affected.

RECEIPT AND ATTACHMENTS

The recipient is asked to compare the subject address on the cover with the property under contract before acknowledging receipt. Receipt does not signify that every question has been answered to the recipient's satisfaction or that any investigation right has been waived. Continuations referenced by a response form part of the delivered record; an unattached reference should be requested before relying on the response. Estimates of age or cost are identified as recollections unless supported by an invoice. Neither a checked response nor the absence of a comment determines insurability, permitted use, market value, or the condition of another component not addressed in that response.

SELLER RESPONSE AND BUYER RECEIPT

Respondent/preparer: /s/ Jamie Ellis — simulated acknowledgment, August 24, 2026 13:10.

Buyer receipt: /s/ Taylor Morgan — simulated receipt, August 24, 2026 18:25; receipt is not a waiver.