

LEAD-BASED PAINT APPLICABILITY NOTICE

Transaction 48292 · v1 · Page 1 of 2

CONSTRUCTION-YEAR ENTRY

Property 77 Juniper Lane, Harborfield; APN 084-221-019; construction year recorded as 1988 in the supplied property profile. Election for this fictional packet: pre-1978 lead-based-paint disclosure path not applicable on the stated construction year. The entry is an applicability screen, not a laboratory finding that paint or soil contains no lead. Seller has not supplied a lead inspection, risk assessment, or abatement certificate.

SUPPORTING RESPONSE AND LIMITATIONS

Seller reports no knowledge of an earlier dwelling incorporated into this structure and has not supplied original permit drawings. If an assessor correction or other credible record indicates pre-1978 housing, the applicability entry must be revisited and the appropriate disclosure process obtained. Do not create a buyer waiver of an inspection opportunity from this not-applicable election. No test result is inserted in the seller-knowledge field.

SELLER'S CONTINUATION — PRIOR WORK

During the first winter after purchase, wind-driven rain reached the interior sill of the rear bedroom window. A glazing contractor renewed the exterior seal in April 2021. Seller observed no recurrence during subsequent ordinary rain but did not open the wall cavity or obtain a mold assessment. In June 2023 a plumbing contractor replaced the kitchen faucet and flexible supply connectors; no relocation of a drain or supply line was included. The service invoices are identified in the repair index as R-04 and R-09. The seller does not possess drawings for the original construction and cannot identify concealed piping materials throughout the residence.

DELIVERY NOTATION

Prepared August 24, 2026 and delivered with the construction-year source reference. Buyer receipt records delivery of the applicability entry only. Renovation safety and occupational exposure are separate questions from the resale disclosure screen; a proposed contractor should evaluate its own work requirements. No promise about the composition of replacement windows, imported fixtures, or later paint is made by the construction-year entry.

KNOWLEDGE LIMITS AND RECORDS DELIVERED

Responses concern the seller's actual recollection during occupancy and are not a representation that an unobserved condition cannot exist. A response of 'not known' is different from a negative test result. Roof surfaces, foundation cavities, underground lines, and areas behind stored belongings have not been opened for purposes of these responses. Service papers delivered with the packet are identified by date rather than adopted as the seller's independent expert opinion. Buyer may ask follow-up questions

LEAD-BASED PAINT APPLICABILITY NOTICE

Transaction 48292 · v1 · Page 2 of 2

KNOWLEDGE LIMITS AND RECORDS DELIVERED — CONTINUED

through the representatives and may employ qualified specialists within the investigation arrangements. Later knowledge of a material change shall be conveyed in a dated supplement identifying the earlier response affected.

RECEIPT AND ATTACHMENTS

The recipient is asked to compare the subject address on the cover with the property under contract before acknowledging receipt. Receipt does not signify that every question has been answered to the recipient's satisfaction or that any investigation right has been waived. Continuations referenced by a response form part of the delivered record; an unattached reference should be requested before relying on the response. Estimates of age or cost are identified as recollections unless supported by an invoice. Neither a checked response nor the absence of a comment determines insurability, permitted use, market value, or the condition of another component not addressed in that response.

SELLER RESPONSE AND BUYER RECEIPT

Respondent/preparer: /s/ Jamie Ellis — simulated acknowledgment, August 24, 2026 13:10.

Buyer receipt: /s/ Taylor Morgan — simulated receipt, August 24, 2026 18:25; receipt is not a waiver.