WORK INSTRUCTIONS **PROPER TAPING PROCESS**			ZEBRA Zebra Technologies
Work Instruction No.			
Revision No. 01	Site Code WI03	Page 1 OF 6	

1. OVERVIEW

This work instruction provides instructions on how to use a tape gun properly and properly tape a box using the standard method (I-Method) or H-Method.

2. TAPE GUN

✓ When a tape gun is not being used, it must be placed in a stable area.

1. Be aware of the serrated blade when replacing the roll of tape.

2. When using the tape gun, keep the tape gun away from the body while taping and tearing off the tape.



3. The hands should not be under the tape gun.

This document contains proprietary information which is the exclusive property of Zebra Technologies Corp.

The most recent version of this document is located on the ISO Library.
Verify revision number before use.

3. I METHOD (STANDARD TAPING)

- ✓ I-Method involves a single layer of tape in the middle of the box.

1. Fold the box into shape; fold the two smaller flaps first and then the two larger ones, ensuring they connect in the middle.
2. Tape down the long horizontal seam in the middle (where the flap edges join).
   - ✓ Ensure that a 2-inch overhang is left on each side of the box.

4. H-METHOD TAPING

- ✓ H-Method involves taping the edges on either side of the box (the shorter vertical seams).
- ✓ This is the main form of taping for small parcel shipments that are being overpacked.

1. Fold the box into shape; fold the two smaller flaps first and then the two larger ones, ensuring they connect in the middle.
2. Tape down the long horizontal seam in the middle (where the flap edges join).



3. Press the tape firmly to the cardboard surface so it adheres well.
4. Apply a strip of tape to the side vertical seams, leaving a 2-inch overhang on the sides.



This document contains proprietary information which is the exclusive property of Zebra Technologies Corp.

The most recent version of this document is located on the ISO Library.
Verify revision number before use.

5. Pinch the tape at one corner so it forms a triangle. Do the same on the other corner. Fold the flap of tape down and press it firmly to the cardboard.

✓ Do the same with the other side of the box.



2. ACCEPTABLE VS UNACCEPTABLE TAPING

ACCEPTABLE

UNACCEPTABLE

✓ If any boxes are taped like the pictures in unacceptable taping, please correct them.

This document contains proprietary information which is the exclusive property of Zebra Technologies Corp.

The most recent version of this document is located on the ISO Library.
Verify revision number before use.

3. SUPPLIER ORIGINAL TAPE

✓ Original supplier tape, as shown below, does not need to be reinforced with regular tape unless the supplier tape was cut through.

4. HOW TO LOAD THE TAPE DISPENSER

1. Set the tape gun on a flat surface, with the open wheel compartment pointed upwards.
2. Slide a new toll of tape onto the tape wheel. Press firmly onto the spokes of the wheel until it comes to a stop.



3. Line the tape with the roller. Rotate the tape of roll until the loose end is hanging under the roller at the front of the gun.

This document contains proprietary information which is the exclusive property of Zebra Technologies Corp.

The most recent version of this document is located on the ISO Library.
Verify revision number before use.

4. Guide the tape up and over the roller. The tape should rest flat against the roller with no folds or wrinkles and cut off the excess tape.





✓ Keep your hands clear of the blade while pulling the tape through.

✓ Some tape guns have a small lever near the handle that helps hold the tape in place. You may need to hold this lever down until you successfully load the dispenser.

5. Adjust the tension knob. The tension knob determines how easily the tape unwinds.



✓ If you want to tighten it, twisting it clockwise will add extra resistance. To loosen it, turn it counterclockwise, and the wheel will rotate more quickly.

5. REFERENCES

Document #	Document Title
N/A	N/A

5. REVISION HISTORY

The following table lists all revisions (including the original document) to this procedure, the date, and the reason for the revision.

Rev.	Rev. Date	Description of Change	Revised By
01	03/26/23	Original issue	A. Cabrera
02	11/14/23	Added the standard method of taping and the how to load tape dispenser instructions.	A. Cabrera

This document contains proprietary information which is the exclusive property of Zebra Technologies Corp.

The most recent version of this document is located on the ISO Library.
Verify revision number before use.