Uplink interference sweep - SEA-RAN-001

Date: 31 Oct 2026, 10:00-10:30. Analyser: handheld, directional antenna.
Uplink noise floor east sector: -88 dBm (normal -105 dBm).
Peak: 1712.4 MHz, narrowband, continuous, strongest at bearing 85 degrees.
Source found: unlicensed cellular booster in a coffee shop ~180 m east.
Booster switched off by owner at 10:25. Uplink RSSI back to -104 dBm at 10:26.
VSWR at radio unit: 1.2 (normal). Antenna and feeders in good condition.
Recommendation: report to FCC enforcement; no change needed on the cell.