

Vérification de base : CHECKLIST avant escalade

Use this guide to:

- Collect the required evidence for every case: a clear problem statement, VIN, software/app version screenshot, network status, explicit customer consent to use the VIN for tests, and an error screenshot or video with a visible timestamp. Reference the Basic Verification checklist before proceeding.
- Follow the scenario-based checklists for: MYBRAND application errors, Service Activation issues, HVAC/Charge remote commands, Account Management issues, and Pairing issues.
- Validate prerequisites and data consistency across involved platforms (e.g., eligibility and offers in CNR; data sharing, bootstrap, communications and consistency in VCPS; ingestion and activation workflow in CVC; gateway and activation flows in ASAP; account and garage status in RTC; error traces in Kibana).

By applying these standard checks upfront, support teams reduce back-and-forth, accelerate root cause analysis, and improve first-time-right resolutions. Please ensure customer data is handled in compliance with Renault Group policies and local regulations, and confirm consent before using a customer's VIN for testing.

Standard required checks for all issues :

- Clear description of the issue
- Adresse MYB du client
- VIN
- Software version picture(Should end with .prd user and not sit user: resolution action check article [Vérifications de base : Connectivité du Véhicule](#))
- Network status (Should not be disconnected [Vérifications de base : Connectivité du Véhicule](#))
- The customer's approval to use his VIN for tests
- Picture of error
- Verification de base ([Vérifications de base : Connectivité du Véhicule](#))

Checklist for cases reopened by L1 after response from L3 Offboard :

*****Clear description of where the issue still occurs*****

1. Verify that a **new** screenshot is attached
2. Check that the screenshot is **timestamped** (test date and time)
3. Verify that the actions requested by L3 have been followed :
 - a. Check whether the **IVI reset** has been performed on CVC
 - b. Check whether a **drive cycle** has been completed (Datastudio)
 - c. Check whether **48 hours** have passed before re-escalation
 - d. Route the case to L3 DEASMM team if requested by L3 SDSM

For MYBRAND errors:

Hello L1,

We kindly ask you to send us the following details to help us investigate and resolve the problem efficiently:

1. **A screenshot or video** of the issue, including a visible timestamp.
2. **Exact date and time** when the issue occurred.
3. **MYBRAND Application Version**
4. **Pays de l'utilisation**
5. **Phone details:**
 - Phone model and brand
 - Operating system (Android or iOS) and version
6. **Last time the application worked properly**
7. **Detailed steps:** Please describe step-by-step what you were doing before the issue occurred.
8. **Network (Is the customer on WIFI or 4G/5G)**
9. **Problem frequency:**
 - Occurred once
 - Happens randomly
 - Occurs every time you use the application

Best regards

L2

For service activation issues :

*****Clear description of issue*****

In CNR

1. The VIN is Eligible for connected services
2. The VIN is eligible for offers in CNR
3. Are the offers created in CNR

IN VCPS

1. The Car's delivery date
2. Datasharing is ON (Last activation date)
3. The communications IVI IVC are recent
4. VIN is bootstrapped
5. Is the Data consistency ok for IVI and IVC
6. Is the PBO activated: YES (IVI Push Button 200)

IN CVC :

1. Is the VIN is ingested in CVC
2. Is the bootstrap auto inventory launched
3. Are the services in activation in progress in campaign history and service execution history in CVC
4. Is there is any previous activation/deactivation failed in CVC

In ASAP

1. Check Car Gateway in vehicle state
2. Is the SSA already launched in ASAP
3. Are the MANAGED_SERVICES_ACTIVATION triggered in ASAP

For HVAC/CHARGE issues :

*****Clear description of issue*****
*****All previous service activations and standard checks should be done*****
*****MyBrand checklist*****

Confirmation of Onboard functioning (Instant or programmed)

In VCPS

1. Check Diagnostic LKCD UID's last update time and value
2. Check remote command requests (Check Code interpretation in HVAC and CHARGE article)
3. Did you launch the reactivation of the service ? (No need to relaunch if L1 done it before)

Hello L1,

Please ask the customer to follow the steps below :

The goal is to identify any issues with the charge scheduling onbaord :

1. Schedule a program on the vehicle to start in 5 or 10 minutes.
2. Go back to the application and schedule the same program also (also in 5–10 minutes) =>Let the program run until execution.
3. After the execution, the customer can create a new program of their preference in the application to confirm if it is correctly taken into account.

After this, we need the customer to provide feedback on the results, specifically:

---Does the program work on board?
---Did they receive a notification saying that the charge started if it works?
---Did the program work without notification?
---Or did it fail to function at all?

Thank you for your feedback.

Best regards,
L2

For Account management issues :

*****Clear description of issue*****
*****MyBrand checklist*****

IN RFORCE :

1. Check account status : Active
2. Compare account name and MYB user name
3. Check ownership status active (Should be the same name as account name)
4. Compare Email address on MyR/MyD Info and one shared by L1

IN RTC :

1. Le rattachement du compte
2. Etat Gigya ID

Action client :

1. Test sur un autre telephone
2. Acceptation des cookies

For pairing issues :

*****Clear description of issue*****
*****All previous service activations and standard checks should be done*****

Prérequis de vérification d'appairage CCS1

- 21 activated
- PBO : at least one service remote car dashboard in confirmed status

Prérequis de vérification d'appairage CCS2

- 21 activated
- No need for PBO to be fully activated
- Factory reset Done by customer

Prérequis de vérification d'appairage ULC

- UID 509 (for Medianav)

In CVC

1. Is the VIN is ingested in CVC
2. Is auto inventory launched
3. Verification du push message

In VCPS

1. Datasharing is ON (Last activation date)
2. Is the Data consistency ok for IVI and IVC
3. VIN is bootstrapped
4. The communications IVI IVC are recent
5. Is the pairing method defined in VCPS
6. Is the PBO activated (CCS2)

In RTC

1. Is the MyRenault active in RTC and VIN added to Garage

In KIBANA

1. Do we have any errors on Kibana regarding the pairing steps (pop-init, valid-pop...)