

- Operating system (Android or iOS) and version
- vi. Last time the application worked properly
- vii. Detailed steps: Please describe step-by-step what you were doing before the issue occurred.
- viii. Network (Is the customer on WIFI or 4G/5G)
- ix. Problem frequency:
 - Occurred once
 - Happens randomly
 - Occurs every time you use the application

Best regards

L2

Check des LKCD

Check de l'UID 202 - Mileage and Fuel Level sur VCPS les données doivent être récentes

RENAULT CLIO V

Vehicle details page

Subscriptions & services

Data consistency

Connected services information

Notifications

UID 202 - Mileage and Fuel Level

Service status

● Activated

Contract status

● Ongoing

Fuel autonomy

210 km

Updated on - 09/03/2026 06:23

Fuel level

11 L

Updated on - 09/03/2026 06:23

Total mileage

21319.77 km

Updated on - 09/03/2026 06:23

UID 362 - Charging status

Service status

● Not applicable

Contract status

● No contract

Charge status

No data

No data on the date of update

System status

No data

No data on the date of update

ev Charge plug connected

No data

No data on the date of update

Check des communications sur CNR

Vérifier que les communications sont récentes et datent de moins de 72 heures.

Connectivity status			Inventory data	
Last IVI connection: 2026-03-09T06:25:29Z			IVI version	
Last IVC connection: 2026-03-09T06:21:59Z			283C37565R_RNF2	
Last SIM connection: 2026-03-09T07:03:23Z			Last update: 2025-07-18T14:45:21Z	
Last MQTT message received IVI:			IVC version	
2026-03-09T06:25:29Z			282777931R	
Last MQTT message received IVC:			Last update: 2025-06-16T15:19:29Z	
2026-03-09T06:21:59Z			UCD version	
			02.02.22.03	
			While List	
			00.01.11	

Réactivation du service

Lancer une réactivation du service Véhicule Odometer Status sur ND, et demander au client de faire une ignition et check for updates.

Template

Hello L1 team,

We have restarted a service synchronisation : Activation is in progress

Please ask user to do the following in a good network connectivity area within the 48h after the sync start

- Start the vehicle, and keep the vehicle ON for at least 5 mins.
- Then turn OFF the vehicle and start again, so the activation of service is successful

Once completed, can you also ask customer to perform a "check for update" through his onboard system screen ?
It will force the system to try and connect again to Renault's server to get back information

If the issue persists, please revert back to us

Thanks & regards
L2 team

Vérifier si le véhicule roule

Si confirmation que le véhicule est bien connecté et roule, mais la valeur de l'autonomie reste ancienne ou ne s'affiche pas sur l'application

escalader le ticket à **SDSM** afin que l'équipe **Aeris** puisse effectuer les vérifications.

TECHOPS : AUTONOMY_XX (Incoherent ou Missing)

Pour les cas clients à 0km dans champs autonomie sur des véhicules SW400 (SCENIC, DUSTER) : **TECHOPS** à utiliser : **IVC error with range effect**