

Rlink - applications

Liste à alimenter

- **France Info TV** : Toujours dispo sur le store mais flux RSS désactivé, **donc App ne fonctionne plus** (cf ticket 4-13004448)
- **Coyote** : Besoin de connectivité pour le bon fonctionnement.
- **Fuel prices** : retired
- **Dealer finder** : retired
- **Email** : currently only available for R-Link 1 devices .
- **R-Link Store** : as of August 31st 2024, the R-Link Store has closed its digital doors. As such, access to the onboard app may have been disconnected.
- **RS Monitor** : D'après ce que nous savons, la boutique R-link n'est malheureusement plus disponible. Nous recommandons au client d'essayer d'installer l'application à l'aide de la boîte à outils R-link2. La boîte à outils devrait reconnaître votre véhicule et vous proposer des mises à jour et des applications disponibles.

==> Si le problème persiste, veuillez l'escalader vers le **L3 ATC** (l'ATC L3 peut le résoudre en forçant la mise à jour pour installer le moniteur RS à partir de Toolbox): L'équipe L3 effectue les actions nécessaires à son niveau afin que le client puisse le télécharger directement depuis sa boîte à outils.

Si cela ne fonctionne pas, nous suggérons au client de procéder comme suit :

Pour le fichier ZIP, vous devez le joindre dans la section des pièces jointes.

Hi L1,

Please find the procedure:

Download the ZIP file

Open the email or the case folder where the ZIP file is attached.

Download the file to your computer or USB drive.

Unzip the ZIP file

On Windows: right-click Extract All...

On Mac: double-click the ZIP file

On mobile/tablet: use a decompression app (e.g., WinZip, RAR, iZip, etc.)

After extraction, you will get a folder containing several files.

Locate the Rlink folder in the Fingerprint system

Connect the device or access the vehicle's storage according to the manufacturer's instructions.

Navigate to the folder named fingerprint, then to Rlink inside it.

Copy the contents of the ZIP into the Rlink folder

Select all the files extracted from the ZIP.

Copy them into the Rlink folder.

Confirm that the files are correctly replaced or added to the existing files (if prompted).

Verify that the files are present

Open the Rlink folder and check that the new files appear.

Restart the system (if necessary)

Some vehicles may require a restart of the Rlink system to recognize the added files.

Follow the manufacturer's instructions to restart or reset the system if indicated.

Best regards

L2