Feature Correlation and Dimensionality Analysis
Stress Detection (WESAD + Empatica E4)

Feature Correlation Matrix



Feature-Target Correlations



PCA: Stress vs Baseline Separation



PCA Explained Variance