

If the cooling fan of Aux. 3 motor went out, do the following steps

1. Turn off the breaker 150Q3 in MCC room F16 cabinet
2. Let operator use Aux. winder to bring the line up.
3. After line brought up, change the cooling fan out.
4. Turn on the breaker 150Q3