
(a)
$\omega = Gu$, G from the step to 0.6
Raised
Lowered
stop
0.22
start
0.34
Steady ω (rad/s)
Duty u
(b)
t_s
t_r
0 to 0.6
0.6 to 0, mirrored
Fitted models
$|\omega - \omega(0)|$ (rad/s)
Time from the command (s)