MONTHLY SAFETY BULLETIN NO — April -2025

(HQ SAFETY BRANCH)

					(HQ SAFETY BRANCH)
S.N	DATE	DIV	DESCRIPTION	CAUSE / SHORTFALL	ACTION
1	20.02.2025 (unusual Incident) 13.00 hrs	НҮВ	LP of T. No. 77653 DEMU pass while on run between GJWL — SIPT stations observed obstruction in track i.e., concrete block (earth pit) and lid on top of the rails at Km 31/5-7 and stopped the train before the obstruction by applying Emergency brake and informed to SM (CMS abnormality).	Miscreant activities	 Divisions to identify such vulnerable locations and to enhance security at those locations. Frontline staff shall be vigilant and shall report any suspicious activities promptly to the concerned authorities.
2	01.03.2025 (unusual Incident) 04.00 hrs	NED	LP of T. No. BCNHL Empty Goods while on run between Nagarsol (NSL) – Ankai killa (ANK) stations, at Km 21/2- 3 noticed JCB arm infringing the track and stopped by applying Emergency brake.	 JCB operator failed to take proper precaution before handling the machine which resulted into JCB arm inadvertently turned towards the running line and infringed the moving Goods train. The JCB operator, started the shifting process at 4.00 am earlier than the usual working hours (i.e, 06.00 am) without information to any railway officials 	 Detailed investigation shall be carried out and action shall be taken against staff responsible. Private Machine operators and Contract staff shall be counselled to avoid such incidences in future. Divisions to closely monitor and ensure that proper work site protection measures are taken while working near the track with machinery. Effectiveness of the barricading provided also to be checked.
3	09.03.2025 (Other Train Accident) 23.11 hrs	GNT	At Gajulapalli (GZL) Station, while DN BOXN/N- 67 Empty Goods train passing through, its 3 rd wagon rear truck both wheels and 4 th wagon all wheels from Train Engine derailed after passing Starter signal.	officials. Cattle run over -barricading not done by Construction Organization before dismantling existing tie bar fencing for doubling work.	 Divisions to carry out a special drive to identify such vulnerable locations and to take preventive measures to arrest recurrence of such incidents. Awareness programs shall be organised to educate the villagers to avoid such incidents. Open line P.Way staff to monitor the construction activities to avoid recurrence of such incidents.

MONTHLY SAFETY BULLETIN NO — April -2025

(HO SAFETY BRANCH) S.N DATE DIV DESCRIPTION CAUSE / ACTION **SHORTFALL** 4 19.03.2025 SC LP of T. No. DN GWD Miscreant activities Divisions to conduct survey (unusual Goods while on run between to identify such locations Incident) Lingampet Jagityal (LPJL) and to remove loose and 21.45 hrs Koratla (KRLA) stations abandoned material from observed obstruction the decommissioned / closed track i.e., Cement bench on stations to prevent similar track at Km 91/5-6 and incidents. stopped the train before the Security / Patrolling shall be obstruction by applying stepped up at identified such Emergency brake locations. informed to SM. • Frontline staff shall be vigilant and shall report any suspicious activities promptly to the concerned authorities. 23.03.2025 5 **GNT** While T. No. 67247 MEMU Cattle run over Divisions to carry out a (Misc was on run between MAG -Entering of stray herd special drive to identify such Accident) NBR stations, MC 400033 of cattle unexpectedly vulnerable locations to take 21.50 hrs (leading) front trolley two on the track preventive measures to avoid wheels derailed at km 17/17 recurrence of such incidents. due to cattle run over. No Awareness programs shall be injuries to any passengers. organised educate to the villagers avoid to such incidents. 25.03.2025 6 SC LP of T. No. UP 12295 Exp. Licensed Material Trollies shall be Porter (unusual while entering onto Platform placed the trolley secured properly to avoid Incident) No. 2 at WL station observed with Luggage on PFrecurrence of such incidences. 01.02 hrs obstruction in track i.e., At important stations, regular without proper Luggage Trolley between securing which rolled checks shall be carried out by Platform and the track and and came on to the Supervisory SMs, TIs, CIs. stopped the train before the track. obstruction by applying License Porter Emergency brake and IRCTC vendor used informed to SM. the trolley unauthorisedly to transport the material. 27.03.2025 TMR of DN BCN Goods **BZA** • SM/CLX allowed the All SMs, LPs and TMRs shall (unusual entered in CMS that LP did train to start without be counselled to ensure that Incident) not follow SR 30 Kmph at km issuing the updated the latest CO is issued to crew 14.30 hrs 406/38-40 between Tenali caution order to LP. while starting the trains. Duggirala stations. He LP/BZA started the Division to carryout detailed informed LP about SR 30 train CLX investigation and appropriate from Kmph in walkie-talkie and without ensuring the action shall be taken against also applied emergency brake updated caution staff responsible. to alert LP. Same informed to order. punctuality and **TMR** counselor.

All Divisions are advised to give wide publicity through special instructions & take suitable corrective action at their end.

No. Safety.387/Monthly Safety Bulletin/Vol. II Dated 10.04.2025

(K Venkatramana Reddy)

Principal Chief Safety Officer

Copy to Secy. to GM, AGM, PCOM, PCME, PCEE, PCSTE, PCSC, PCE & PCCM

Copy to DRM/SC, HYB, GTL, GNT, BZA & NED.

Copy to Sr.DSO/SC, HYB, GTL, GNT, BZA & NED.