SOUTH CENTRAL RAILWAY



Office of the Divisional Railway Manager/Safety Fourth Floor, Sanchalan Bhavan SECUNDERABAD

E-mail: srdsosecunderabad@gmail.com
Mob No.9701371750

No. C/SFY-5/SD-20/May-1/2025

Date 09.05.2025

SAFETY DRIVE May - 1 /2025

Sub: Rly. Board's Safety Calendar Drive for the month of May' 2025 -reg. Ref: 1.PCSO/SC Ltr No.Safety.387/safety Drives/Rly.Bd/Vol.XIII dt 06.05.25 2.Rly. Board Lr. No.2025/Safety(Imp)/3/Safety Calendar dt 13.03.25

Railway Board vide letter cited under reference-2, advised that a Safety drive for one week period starting from 12.05.2025 to 18.05.2025 to be conducted on the following aspects for the month of May'25.

Electrical	TRD: Drive for Bonding such as open or loose bonds, bond
	missing etc
	Crew: Availability of Safety equipment in locomotive
	Traction: Above roof drive such as cleaning joint with TRD staff
,	etc
Mechanical	Drive on fire protection measures in coaches including working of fire detection system in AC coaches, fire detection and suppression systems in pantry cars and power cars. Check the locking of automatic suppression system magnet valve in FDSS and locking arrangement for brake system isolation cut out cock in FSDS
	Check the locking of automatic suppression system magnet valve in FDSS and locking arrangement for brake system isolation cut out cock in FSDS
	Availability, condition and cross-check of schedule overdue of portable fire extinguishers provided in coaches
. I	Process audit of spring section in workshops.
S&T	All veeder counters in stations should be cross checked with register for matching of number and proper reason
	Obstruction test of interlocked point as per SEM to ensure their safe working
	Ensure that roof of relay room, IPS Room and Battery rooms are clean and water drains are not chocked

	Proper working of lighting and surge protection devices
Operating	Updating of SWR as per the physical condition of Yard
	SWR should be updated from time to time with the last date of updation and if any further change has been made, the correction slip issued after the last updation should be available
	The station working diagram should be available and it should confirm to the existing layout of the station
	The station working rule should be available with station master,
	cabin incharge and vard master
Engineering	Drive for checking Hot Weather Patrolling of track.

After completion of the drive, a consolidate report from each branch item wise checks, deficiencies noticed and no of staff counselled to be submitted to this office by 19.05.2025 as per the Annexure-A, B & C for appraising to DRM and PCSO office.

Encl: Annexure-A, B & C

Note: All BOs are requested to ensure that details of deficiencies noticed and its attention particulars with photos to be submitted both hard & soft copy मेरहिस. त

for appraising to PCSO office as advised.

[ए. सुरेश]/ [A. Suresh] Sr. DSO/SC

Copy: DRM/SC for kind information. ADRM/O & ADRM/I for kind information. Sr DEN/Co, Sr DEN/N,W&S, Sr DME/Co, Sr CDO/SC &HYB, Sr DEE/M, Sr DOM, Sr DSTE, Sr DEE/TRSO, Sr DEE/TrD, Sr DEE/ELS/LGD, Sr DEE/ ELS/KZJ, Sr DME/DLS/KZJ & DEN/C for information and necessary action pl.

Format for the week long safety drive for the month of May'25 (12.05.2025 to 18.05.2025)

Annexure - A
Week long safety drive for the Month of March'25

0.11	1101111	Juicty	dire for f	ne month	oi march	725		
S.No.	Dept	Elec	Mech	S&T	Optg	Engg	Safety	M-4-1
1	No. of inspections done by officers(TRD+TRSO+TRS)				- Opis	Diigg	Salety	Total
2	No. of inspections done by supervisors(TRD+TRSO+TRS)							
3	Total No. of inspections done.							
4	Total No. of Checks conducted							
5	Total No of staff counseled							
6	No. deficiencies found							
7	Total No. of compliances done.		and the same of th					
8	TDC for balance deficiencies.							

Annexure-B

List of items to be checked during the Safety drive

1. ELECTRICAL

Dept	Observations to be done on	Total No. of checks done	Total No. of staff counsel ed	Total No. of deficienci es observed	No. of deficien cies attende d	Bala nce	Action taken / (TDC)
TRD	Drive for Bonding such as open or loose bonds, bond missing etc	5		3332704	u		
TRACTI ON	Above roof drive such as cleaning joint with TRD staff etc						
Crew	Availability of Safety equipment in locomotive						
Grand Total							

2. Mechanical:

Observations to be done on	m . 1					
o be to be done on	Total	Total	Total No.	No. of	Bala	Action
	No. of	No. of	of	deficien	nce	taken/
	checks	staff	deficienci	cies	1100	/TDC
	done	counsel	es	attende		, 150

	ed	observed	d	
		,		
Orive on fire protection measures in coaches including working of fire detection system in AC coaches, fire detection and suppression systems in pantry cars and power cars. Check the locking of automatic suppression system magnet valve in FDSS and locking arrangement for brake system isolation cut out cock in FSDS				
Check the locking of automatic suppression system magnet valve in FDSS and locking arrangement for brake system isolation cut out cock				
in FSDS Availability, condition and cross- check of schedule overdue of portable fire extinguishers provided				
in coaches Process audit of spring section in workshops. Grand Total				

3. S & T Observations to be done on	Total No. of checks done	Total No. of staff counsel ed	Total No. of deficienci es observed	No. of deficien cies attende d	Bala nce	Action taken/ planned/ TDC
All veeder counters in stations should be cross checked with register for matching of number and proper reason Obstruction test of interlocked point as per SEM to ensure their safe			,			
working Ensure that roof of relay room, IPS Room and Battery rooms are clean and water drains are not chocked Proper working of lighting and surge protection devices						
Grand Total			8			

4. Operating Observations to be done on	Total No. Total No. Total No. of checks of staff of	No. of Bala Action taken / deficienci nce planned /TDC
------------------------------------------	-----------------------------------------------------	--------------------------------------------------------

	done	counsele d	deficienci es observed	es attended	
Updating of SWR as per the physical condition of Yard					
SWR should be updated from time to time with the last date of updation and if any further change has been made, the correction slip issued after the last updation should be available					
The station working diagram should be available and it should confirm to the existing layout of the station					
The station working rule should be available with station master, cabin incharge and yard master					
Grand Total					

5. Engineering:

Observations to be done	Total No.	Total No.	Total No.	No. of	Bala	Action taken /
on	of checks	of staff	of	deficienc	nce	planned /TDC
	done	counseled	deficiencie	ies		
			s observed	attended		
Drive for checking Hot		*			640	
Weather Patrolling of track	_7	9	6			
Grand Total						

Annexure-C

- 1) Details of depart-wise major deficiencies noticed and attended are as mentioned below (important photograph should be attached / included in report):
- 2) Details of depart-wise major deficiencies noticed and yet to be attended with TDC are as mentioned below (important photograph should be attached / included in report):

Sr.DSO/SC