Congratulations! You passed!

Grade received 100% To pass 80% or higher

Go to next item

1.	In order to apply the method of least squares, it is necessary to know the measurement noise variances. True	1/1 point
	 False Correct Correct! Least squares can be applied to minimize a squared error criterion, without necessarily knowing the noise characteristics of the measurements. 	
2.	For the method of least squares, select any/all that apply. The squared error criterion and least squares method can be applied directly to nonlinear measurement models. Given a linear observation model, the parameters that minimize the squared error criterion can be found by solving the normal equations.	1/1 point
	Correct! However, there is an additional criterion required for the solution to be valid. For more details, review the "Squared Error Criterion and the Method of Least Squares" lecture in this module. ✓ The method was pioneered by Carl Friedrich Gauss. ✓ Correct Correct! The least-squares method is usually credited to Carl Friedrich Gauss ✓ (1795).	
3.	Lesson 1 referred to the Jacobian matrix, ${\bf H}$, which relates the parameters of the linear model to the measurements. Assume that, for a particular problem, our model has three parameters and we obtain ten measurements - what size should the Jacobian matrix be?	1/1 point
	$ \bigcirc \ \text{The matrix}\mathbf{H} \text{ should be } 3\times 10 \text{ in size}. \\ \\ \bigcirc \ \text{Correct} \\ \text{Right! There is one row in the matrix for each measurement and one column for each parameter.} $	
4.	According to the weighted squared error criterion, the error term corresponding to a measurement with a noise variance of 10 units will be weighted more highly than that of a measurement with a noise variance of 1 unit. True False	1/1 point
	○ Correct Correct! A larger noise covariance means a lower weight (i.e., a less trustworthy measurement).	
5.	In which of these cases would the method of weighted least squares produce valid solutions. Select any/all that apply. Five measurements, six unknown parameters. Five measurements, five unknown parameters, and two different noise variances. Correct	1/1 point
	Correct! We have an equal number of measurements and unknowns, which means the five parameters can be estimated correctly. The non-zero noise variances affect the estimator accuracy, but not the validity of the solution. Ten measurements, two unknown parameters.	
	 Correct Correct! We have more measurements than unknowns, which means the two parameters can be estimated reliably. 	
	Ten measurements, two unknown parameters, and two different noise variances, one of which is exactly zero.	

6. You are measuring the voltage drop V across an electrical component using two different multimeters; one of the meters is known to be more reliable than the other. Which method would you use to estimate the best voltage value from noisy measurements?

1/1 point

Weighted Least Squares

O Least Squares

⊘ Correct

Correct! WLS can handle the possibility of the measurements having different noise levels (variances).