Jame of th	e Gurugulam Skill: WELDING			BATCH:2			Duration of the skill : 2 DAYS
Name of the Gurugulam Skill. WELDING			BATCH:2			Duration of the Skill . 2 DATS	
l) Student [Petails					6) Reflection (Major problems faced/ Trouble	shooting):
NAME : GOKUL S ROLL NUMBER : 7376232AL116					Problems	Counter measures	
DEPARTMENT : ARTIFICIAL INTELLIGENCE AND MACHINE LEARNING						Faced some difficulties while welding	Self understood and resolved
YEAR : I YEAR						Faced some difficulties while grinding	Self understood and resolved
2)Lab Schedule:					Faced some difficulties while making and cutting in proper dimensions	Self understood and resolved	
<u> </u>			Time			Faced some difficulties while designing a	
No. of days	8.45 - 10.25		10.40 - 12.20	1.30 - 3.10	3.25- 4.30		Self understood and resolved
1	Practicing the ARC welding (Meg and Thick welding)		Discuss the given task and start a cutting process	After the cutting process then start welding the given task	Start grinding the welded parts and grind the small particles in the edge		
3)Assessme	ent Schedule:			weiding the given task	Igillia tile siliali particles ili tile eage	7) Photographs of the Lab tasks:	
Date	Time				Photographs		
	8.45 - 10.25		10.40 - 12.20		3.25- 4.30		
29.2.24	Analyze the given task		Design a model and start cutting the pipes in	Start the welding process join the pipes and make a	Grind the unwanted particles in the edge of the		
l) Lab task	details:		the pipes in	pipeo ana make a	Cage of the		
S.No	Name of the task Outcome						
1	Fabrification of metal structure - Book stand Book stand with perfect measurements						
2	Fabrification of metal structure - modern gate	Modern gate with a unique design					
3							
4					The state of the s		
						1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
) Process	Plan & Execution:					100	
Гask no	Proposed Process Plan	Actual Plan executed			9) Knowledge acquired from Lab tasks:		
1	Marking the necessary dimensions and cutting the required size o start welding process join the pipes and finally grind the unwante the frame.	Marking the necessary dimensions and and cutting the required size of the raw materials then start welding process join the pipes and finally grind the unwanted particles in the edge of the frame (cuboid).			To overcome the fear of welding and more interesting to make more things Task 1		
2	Marking the necessary dimensions and measurements and the cu the raw materials then start welding process join the pipes an particles in the edge of the modern gate and make a unique designate.	Marking the necessary dimensions and measurements and the cutting the required size of the raw materials then start welding process join the pipes and grind the unwanted particles in the edge of the modern gate and make a unique design in the interior part of the modern gate finally clean the workspace.			To handle the tools properly and to make a products by using welding process and learn how to cut the raw mater Task 2		