

Figure 9.1: A block diagram for a feedback control system. The reference signal r is fed through a reference shaping block, which generates a signal that is compared with the output y to form the error e. The control signal u is generated by the controller, which has the error as the input. The load disturbance v and the measurement noise w are external signals.