










- PCB Scans

Front



Back





- Assembled a new PCB

- Didn't have a JST connector, so used a cable as a temporary workaround

