```
WindowsWirelessAdapter
+ initiateTimingRequest()
+ refreshCrossTimestamp()
+ registerTimestamper()
+ deregisterTimestamper()
+ initialize()
+ shutdown()
+ attachAdapter()
   IntelWirelessAdapter

    hAdapter

- ct lock

    ct cond

- ct done
- ct miss
```

+ refreshCrossTimestamp()
+ initiateTimingRequest()

+ attachAdapter()+ registerTimestamper()+ deregisterTimestamper()+ IntelWirelessAdapter()

+ calc rollover()

- gp2_last - gp2_ext + initialize() + shutdown()