
Demonstration for BODMAS:

Enter 15 using Keypad in LCD. Because 15th operation is BODMAS.



Then enter the value as described in documentation "COMPLEX CALCULATOR USING ARDUINO" for BODMAS part and then after pressing B as described in documentation. You will get BODMAS result.

