
thoughts on the distance from top of unit to underside of mantel. In this photo is would be approximately 10"