0809 实验


一、实验内容

1.将 INT0—INT7 分别连接到 2 个可变电阻器上,每秒采集一次 0809 转换的数字量,将转换后的数字量和路号在显示器 CRT 上显示,并将转换后的数字量送往 8 段显示,采集 10 个循环后结束。

2.将 INTO 连接到 1 个可变电阻器上,每秒采集一次 0809 转换的数字量 n,要求将电压值 U 显示在 8 段显示器。

二、0809知识

1. ADC0809 的工作过程:



第一步: 首先确定 ADDA、ADDB、ADDC 三位地址,决定选择哪一路模拟信号。第二步: 使 ALE 端接收一正脉冲信号,使该路模拟信号经选择开关达到比较器的输入端。

第三步: 使 START 端接收一正脉冲信号,START 的上升沿将逐次逼近寄存器复位,下降沿启动 A/D 转换。


第四步: EOC 输出信号变低,指示转换正在进行。

第五步: A/D 转换结束, EOC 变为高电平, 指示 A/D 转换结束。此时,数据已保存到 8 位锁存器中。

第六步: OE 信号变为高电平,则 8 位三态锁存缓冲器的三态门被打开,转换好的 8 位数字量数据被输出到数据线上。

如上所述, EOC 信号变为高电平表示 A/D 转换完成, EOC 可作为中断申请信号, 通知 8086CPU 取走数据。在查询传送方式中, EOC 可以作为 8086 查询外设的 状态信号

2. 实验电路图



三、参考程序

;PC7--0809 的 EOC;PC0--8253 的 out1;PA--7 段数码管; PB4--数码管的 S0; PB5--数码管的 S1

DATA SEGMENT

TABLE_LED DB 3FH,06H,5BH,4FH,66H,6DH,7DH,07H
DB 7FH,6FH,77H,7CH,58H,5CH,79H,71H
DB 80H

TABLE_CRT DB 30H,31H,32H,33H,34H,35H,36H,37H
DB 38H,39H,41H,42H,43H,44H,45H,46H

TABLE_KONG DW 0,290H,291H,292H,293H,294H,295H,296H,297H

NUM1 DB 10H NUM2 DW 1010H

DATA ENDS

```
CODE SEGMENT
     ASSUME CS: CODE, DS:DATA
START:
     MOV AX, DATA
     MOV DS, AX
     CALL Init 8253; 地址: 288-28BH,初始化 8253, 使之产生 1s 方波
     CALL Init_8255; 地址: 280-283H,初始化 8255, A 口输出, B 输出, C 口高位输入, C 低入
     CALL WAIT INSPACE; 等待空格键
     MOV CX, 11
     MOV SI, 0
INIT:
     MOV DI, 0
READ INPUT:
     CALL LIGHT_LED ;8 段显示
                    ;读 C 口
     MOV DX,282H
     IN
          AL, DX
     Test AL,01H
                  ;PC0=0?
     JZ READ_INPUT ; PC0=0
           DI;通道号
     INC
     CMP DI, 9
     JZ NEXT_INPUT
     PUSH DI
     SHL DI, 1;乘以 2
     MOV DX, TABLE_KONG[DI]
     POP DI
     OUT DX, AL
     CALL DELAY
     IN AL, DX
                  :高位 AH 低位 AL 中
     MOV AH, AL
     PUSH CX
     MOV CL,4 ;读高 4 位 AH 中
     SHR AH,CL ;读高 4 位 AH 中
     POP CX
```

AND AL,OFH ;低位 AL 中

```
MOV NUM2, AX
     MOV AX, DI
     MOV NUM1, AL
     CALL CRT; CRT 显示
WAIT_TIMEOUT:
     MOV DX,282H ;读 C 口
     IN AL,DX
     AND AL, 01H
     JNZ WAIT_TIMEOUT ;PC0=1
     JMP READ_INPUT
NEXT_INPUT:
     DEC CX
     CMP CX,0
     JZ FINAL ;CX=0?
     JMP INIT
FINAL:
    MOV AH,4CH
    INT 21H
DELAY PROC NEAR
     PUSH DX
AGAIN:
     MOV DX, 282H;读 C 口
     IN AL,DX
     test AL,80H;PC7=0?
     JZ AGAIN ;PC7=0
     POP DX
     RET
DELAY ENDP
LIGHT_LED PROC NEAR
     MOV AL,0H;熄灭
     MOV DX,281H
     OUT DX,AL
     MOV AX, NUM2
```

LEA BX,TABLE_LED;取低位

XLAT TABLE_LED

MOV DX,280H

OUT DX,AL

MOV AL,10H;PB4=1,点亮

MOV DX,281H;

OUT DX,AL

MOV AL,0H;熄灭

MOV DX,281H

OUT DX,AL

MOV AX, NUM2

MOV AL, AH

XLAT TABLE_LED;取高位

MOV DX,280H

OUT DX,AL

MOV AL,20H;送 PB5=1,点亮

MOV DX,281H

OUT DX,AL

MOV AL,0H;熄灭

MOV DX,281H

OUT DX, AL

RET

LIGHT_LED ENDP

CRT PROC NEAR

MOV AL, NUM1

LEA BX,TABLE CRT

XLAT TABLE_CRT;取低位

MOV DL,AL

MOV AH,02H

INT 21H

MOV DL,''

```
MOV AH,02H
      INT 21H
      MOV AX, NUM2
      MOV AL, AH
      LEA BX,TABLE_CRT;取高位
      XLAT TABLE_CRT
      MOV DL,AL
      MOV AH,02H
      INT 21H
      MOV AX,NUM2
      XLAT TABLE_CRT;取低位
      MOV DL,AL
      MOV AH,02H
      INT 21H
      MOV DL,''
      MOV AH,02H
      INT 21H
      MOV DL,''
      MOV AH,02H
      INT 21H
      RET
CRT ENDP
Init_8253 PROC;
       MOV DX,28BH ;8253 控制字
       MOV AL,00100101B
       OUT DX,AL
       MOV DX,288H
       MOV AL,10H
       OUT DX,AL
       MOV DX,28BH
       MOV AL,01100111B
       OUT DX,AL
       MOV DX,289H
       MOV AL,10H
       OUT DX,AL
```

```
RET
Init_8253 ENDP
Init_8255 PROC
     MOV AL,10001001B;控制字 A 出, B 出, C 高入, C 低入
     MOV DX,283H
     OUT DX,AL
     RET
Init_8255 ENDP
WAIT_INSPACE PROC
 NEXT:
     MOV AH,01H
     INT 21H
     CMP AL,20H
     JNZ NEXT
     RET
WAIT_INSPACE ENDP
```

CODE ENDS END START