Flood situation report

Trishuli river corridor · 2026-08-26

Generated: 2026-10-15T02:01:49+00:00

Run 0717d3b1-ac72-48d2-a8bb-8ecb93e9663c · Report c4df360f-9323-4b03-b712-bff588a86357

INCOMPLETE REPORT — partial observations. Unavailable measurements are not zero. Processed optical acquisition dates, Possible surface/debris change

Satellite observations

Before radar acquisition: 2026-08-16T12:21:41.058298Z; After radar acquisition: 2026-08-28T12:21:41.762029Z; Processed optical product IDs: No entries recorded; Processed optical acquisition dates: Unavailable.

Flood and surface-change findings

The recorded findings are Potential new inundation: 0.000 km². and Eligible observation coverage: 13.6 %..

Usable radar coverage stands at Usable paired radar coverage before water-target screening: 97.6 %., while debris assessment is unavailable (Possible surface/debris change: Unavailable.).

Pre-existing water: 0.701 km²; Paired clear optical coverage: 0.0 %; Water-class eligible coverage: 13.6 %; Surface-change-class eligible coverage: 0.0 %.

Surface-change/debris candidates can include other land-cover changes; they are not confirmed debris flows.

Unobserved areas remain unknown. No mapped change does not prove absence of damage.

Potential infrastructure exposure

Potentially exposed assets include Potentially exposed buildings: 0., Potentially exposed road features: 0., and Potentially exposed bridges: 0..

The intersecting road length is Road length intersecting mapped changes: 0.000 km..

Mapped intersection indicates potential exposure, not confirmed damage or destruction.

Modeled settlement connectivity

Modeled loss of access affects Settlements with modeled loss of access: 0. settlements, with Unassessed settlements: 56. remaining unassessed.

Access uncertainty applies to Settlements with uncertain access: 47. settlements, and Already disconnected settlements: 6. were already disconnected.

Connectivity uses a thresholded candidate-overlap closure scenario. Water beneath a bridge does not prove failure. Actual closures remain unverified.

Sources and evidence

Data sources include an OSM snapshot from Historical OSM snapshot: 2026-07-27T08:59:58Z., radar before acquisition on Before radar acquisition: 2026-08-16T12:21:41.058298Z., and after acquisition on After radar acquisition: 2026-08-28T12:21:41.762029Z..

Before radar product id: S1D_IW_GRDH_1SDV_20260816T122141_20260816T122206_004151_007980_B091_COG; After radar product id: S1D_IW_GRDH_1SDV_20260828T122141_20260828T122206_004326_007FA4_C73B_COG; Detection method: Rule-based radar and optical change detection.

Evidence: result.json, extent.geojson and the selected analysis's infrastructure/connectivity layers.

Important limitations

The prototype is educational; satellite estimates require independent field verification (Recorded prototype limitation: Educational prototype. Satellite estimates require independent field verification..).

Satellite revisit gaps, terrain shadow, clouds and vegetation limit interpretation; the system cannot provide minute-ahead warnings.

Incomplete OSM roads, facility operation and routes outside the analysis bounds remain unverified.

Unobserved areas remain unknown. No mapped change does not prove absence of damage.

Population and casualty estimates are unavailable. Field verification and native-speaker Nepali review remain necessary.

Contains modified Copernicus Sentinel data 2026.
Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved.
© OpenStreetMap contributors.
European Union, Copernicus Emergency Management Service data
Educational prototype; independent field verification required.