Flood situation report

Trishuli river corridor · 2026-08-26

Generated: 2026-10-14T08:16:45+00:00

Run 1dfef292-6f22-4d29-b279-d6f92bf8e8ca · Report b97b55b9-cf1c-4d9c-96d6-629c8af99ad6

SYNTHETIC DEMO — not observations or results of the real event.

INCOMPLETE REPORT — unavailable measurements are not zero. Processed optical acquisition dates

Satellite observations

Before radar acquisition: 2026-08-20T00:00:00Z

After radar acquisition: 2026-09-01T00:00:00Z

Processed optical product IDs: SYNTHETIC-S2-BEFORE; SYNTHETIC-S2-AFTER

Processed optical acquisition dates: Unavailable

Flood and surface-change findings

Potential new inundation: 42.080 km²

Possible surface/debris change: 9.080 km²

Pre-existing water: 17.720 km²

Eligible observation coverage: 35.5 %

Paired clear optical coverage: 90.4 %

Surface-change/debris candidates can include other land-cover changes; they are not confirmed debris flows.

Unobserved areas remain unknown. No mapped change does not prove absence of damage.

Potential infrastructure exposure

Potentially exposed buildings: 79

Potentially exposed road features: 7

Potentially exposed bridges: 3

Road length intersecting mapped changes: 6.000 km

Mapped intersection indicates potential exposure, not confirmed damage or destruction.

Modeled settlement connectivity

Settlements with modeled loss of access: 3

Unassessed settlements: 0

Settlements with uncertain access: 2

Already disconnected settlements: 0

Connectivity assumes candidate-intersecting road segments are impassable. Actual closures and physical inaccessibility are unverified.

Example settlements: Demo east village [synthetic/6], Demo upper village [synthetic/10], Demo riverside village [synthetic/14]. Complete list remains in map exports.

Sources and evidence

Before radar product id: SYNTHETIC-S1-BEFORE

After radar product id: SYNTHETIC-S1-AFTER

Historical OSM snapshot: 2026-07-27

Detection method: Rule-based radar and optical change detection

Evidence: result.json, extent.geojson and the selected analysis’s infrastructure/connectivity layers.

Important limitations

Satellite revisit gaps, terrain shadow, clouds and vegetation limit interpretation; the system cannot provide minute-ahead warnings.

Incomplete OSM roads, facility operation and routes outside the analysis bounds remain unverified.

Unobserved areas remain unknown. No mapped change does not prove absence of damage.

Population and casualty estimates are unavailable. Field verification and native-speaker Nepali review remain necessary.

Contains modified Copernicus Sentinel data 2026.
Produced using Copernicus WorldDEM-30 © DLR e.V. 2010–2014 and © Airbus Defence and Space GmbH 2014–2018 provided under COPERNICUS by the European Union and ESA; all rights reserved.
© OpenStreetMap contributors.
Educational prototype; independent field verification required.